

Date: 31/7/2024
Vehicle No: SBT12L
Model: TESLA MODEL 3
Chassis: LRW3F7EL7MC282999
Reg. Year: 2021

NOT Authorised
Put my B4 pain
4 days

Third Party Insurer: AIG
Third Party Veh No: SLU8889Y
Date of Accident: 27/7/2024
Estimator: JONATHAN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER			\$ <i>Per Mr</i> 766.00 ✓
	RR BUMPER LHS REFLECTOR			\$ <i>CM</i> 20.56 ✓
	RR REINFORCEMENT BAR			\$ 271.02 7
	RR BOOT			\$ <i>B4</i> 728.97 ✓
	RR BOOT EMBLEM (LOGO)			\$ <i>na</i> 37.38 —
	RR BOOT EMLBEM (DUAL MOTOR)			\$ <i>na</i> 29.90 —
SUB TOTAL				\$ 1,853.83
Less 10%				-\$ 185.38
PARTS TOTAL				\$ 1,668.45

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>na</i> 50.00 —
	CAR WRAP			\$ <i>(Bill)</i> 850.00 7
S/N TOTAL				\$ 900.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas	\$ 800.00 40
To perform wiring checks on electrical systems	\$ 30.00 2.
To remove, putty, repair, sand and respray affected areas	\$ 600.00 4.
To remove, replace & refix bumper sensors	\$ 30.00 ✓
To remove, replace & reinstall Bootlid inner mechansim	\$ 30.00 ✓
To perform Adas Checks, Calibration & Programming	\$ 200.00 7

LABOUR TOTAL	\$ 1,690.00
TOTAL	\$ 4,258.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 59143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9918 | Fax: (+65) 6481 1053

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-09 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

