

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 23 Aug 2024

Preliminary Advice

Vehicle No	: SNQ8395C	Accident Date	: 28/07/2024
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPC24A00240400
Assignment Date	: 01/08/2024	Excess	: S\$0.00
Date of Inspection	: 02/08/2024	Est. Duration of Repair	: 3
Inspection At	: DICKSON AUTO CARE CENTRE PTE LTD (HQ) 29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,351.00	(Estimate \$6,191.00 + Supplementary \$160.00)
Revised Amount	:S\$	776.00	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	776.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	51,328.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,672.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.