

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S: LIM TECK GUAN
436B FERNVALE RD
#15-176
SINGAPORE 792436

ATTN:
Your Ref No: SKK7506Z
Claim Type: Third Party
Accident Date: 26/07/2024
TP Veh Reg No: SLN7058Y

Estimate No: MCI904463
Date: 29 Jul 2024
Policy No: P10082733R05
Veh Reg No: SKK7506Z
Make/Model: TOYOTA PREMIO 1.5F A

SURVEYOR COPY

Not within 11 days Kenneth
11 Sep 24 (23/09/24 - 30/09/24)
Pursuing After Point
4 days

Estimate Repair Cost to Vehicle No :SKK7506Z

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	1 PC	1,536.80	✓
2 REAR BOOT EMBLEM	1 PC	84.10	✓
3 REAR BOOT PREMIO LOGO	1 PC	83.40	✓
4 REAR BOOT LAMP LH	1 PC	385.10	✓
5 REAR BUMPER	1 PC	2,282.80	✓
6 REAR BUMPER SIDE RETAINER LH & RH	2 PC	175.00	X
7 REAR BUMPER CLIPS	15 PC	82.50	✓
8 REAR END PANEL	1 PC	481.00	X
		5,110.70	
	Less 25%	1,277.68	3,833.03
Special Netf			
9 NUMBER PLATE	1 PC	35.00	✓
10 REVERSE SENSOR	1 SET	200.00	X
		235.00	235.00
LABOUR			
11 TO REMOVE AND REINSTALL/REPLACE FRONT REAR BUMPER SENSORS.	1 PC	60.00	X
12 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	301
13 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	4001
14 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL.	1 PC	800.00	4001
		1,720.00	1,720.00



11 Sep 24 833501