Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Date: 13 Aug 2024

Preliminary Advice

Insured Vehicle No : SLN7058Y

TP Vehicle No : SKK7506Z Accident Date : 26/07/2024

Make : TOYOTA PREMIO Assignment Date : 01/08/2024

Date of Inspection : 12/08/2024 Est. Duration of Repair : 4

Inspection At : AH LIM MOTOR COMPANY (AMK)

10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,788.03
Revised Amount	:S\$	4,206.03
Check Items (Estimated)	:S\$	360.75
Total	:S\$	4,566.78

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.