

3 MOTORWERKZ CONCEPT PTE LTD

Not Authorized
in
merc
1/8/24
1/5 \$ 2100
4 days. Etc. phs. Att. Up

Estimate

PAGE : 1/3

YEAR : _____ VEHICLE NO : SMZ5823T
MODEL : HONDA CIVIC CHASSIS NO : MRHFC5650KT000586

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Tail lamp 1/5 340.50 CM	1	\$2,200.00 ✓
2	Rear bumper 617.20 Dis	1	\$1,350.00 ✓
3	Rear bumper side retainer 1/5 45.00 CM	1	\$168.00 ✓
4	Rear bumper reflector 1/5 11	1	\$220.00 X
5	Rear bumper reflector garnish 1/5 48.60 Dis	1	\$280.00 ✓
6	Rear bumper lower garnish 109.20 De	1	\$288.00 ✓
7	End panel 11	1	\$980.00 X
8	End panel top trim 11	1	\$165.00 X
9	End panel inner garnish 11	1	\$220.00 X
10	Exhaust 11	1	\$1,200.00 X
11	Rear floor panel side board 11	2	\$330.00 X
12	Rear fender inner trim 11	2	\$1,240.00 X
13	Rear fender inner shield 1/5 166.80 Torn	1	\$230.00 ✓
14			
15			
16			\$8,871.00
17		Discount 20%	\$1,774.20
18		TOTAL :	\$7,096.80
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			

Estimate

PAGE : 2/3

YEAR : _____ VEHICLE NO : SMZ5823T
MODEL : HONDA CIVIC CHASSIS NO : MRHFC5650KT000586

S/NO	S/N ITEMS	Qty	Price
1	Rear bumper clips <i>all</i>	1 set	\$50.00 <i>30 s/w</i>
2	End panel sealant <i>11</i>	1	\$80.00 <i>X</i>
3	End panel top trim clip <i>11</i>	1	\$50.00 <i>X</i>
4	Rear fender inner trim clip <i>11</i>	1	\$50.00 <i>X</i>
5	Rear fender inner shield clip <i>11</i>	1	\$50.00 <i>X</i>
6	Reverse sensor <i>malfuction</i>	1	\$280.00 <i>200 s/w</i>
			\$560.00
Parts Total :			\$0.00
S/P Item :			\$560.00
TOTAL :			\$560.00

3 MOTORWERKZ CONCEPT PTE LTD

Estimate

PAGE : 3/3

YEAR : _____ VEHICLE NO : SMZ5823T
 MODEL : HONDA CIVIC CHASSIS NO : MRHFC5650KT000586

S/NO	LABOURS	AMOUNT
1	To straighten and panel beat rear frame members, to cut/weld rear portion to remove and refit above parts. 550	\$ 1,000.00
2	To putty, re-spray painting and polish rear affected areas. 700	\$ 1,000.00
3	To rust proof affected rear areas. 17 X	\$ 200.00
4	To remove and install carpet, trim and interior 60	\$ 200.00
5	To remove, install and check reverse sensor 30	\$ 100.00
6	To conduct disgnotic. 11 X	

TOTAL : \$ 2,500.00
 PARTS TOTAL : \$ 560.00
 GRAND TOTAL : \$ 3,060.00

Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____
 Eater: _____

P-132730
 28
 1061.84
 230
 1340
 2631.84
 28
 2105