

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMD 24080009/4np3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM25823T

at Workshop m/s 3 motorworks

of _____

Insured: FBV118E

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \$786

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**

GIA / PR Seen: _____ Consistent? : **Yes** or **No**

Est. Repairs: 4 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 21A \$28045

Vehicle: **IN / OUT**

Veh No: SM25823T Yr Regn: 12/07/18

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or CA

Make: Honda civic 1.6 c.c. 1597

Colour: Blue A/C: **Insured / Std / NI / NA**

Sp.Reading: 131920 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: MRHFC5650KT000586

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi: **Nil / S/Rim / STD A/Rim** or

Tyre Size: **F:** _____

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front 6 **Rear** 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/07/24 D.O.I. 1/8/24

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or

Rear N/S

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
<u>6/8/24</u>	<u>4/5 @ 2100 in Board AM Chg;</u>
	<u>(Red. \$ 8056.80, 79%)</u>

Date/Time, File Pass to?

☐

: **Preli. Report**

1)

☐

: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐

: **Site Insp (\$**

☐

: **Interview (\$**

☐

: **Tech. Invs (\$**

☐

: **Weekend (\$**

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	898J
Vehicle Details	
Vehicle No.:	SMZ5823T
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Aug 2024
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	R16B25510619
Chassis No.:	MRHFC5650KT000586
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,215.00
Original Registration Date:	12 Jul 2019
First Registration Date:	12 Jul 2019
Transfer Count:	1
Actual ARF Paid:	\$20,301.00 10150
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jul 2029
PARF Rebate Amount:	\$14,210.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,009.00
COE Rebate Amount:	\$14,835.00
Total Rebate Amount:	\$29,045.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Aug 2024

OK

3 MOTORWERKZ CONCEPT PTE LTD

Not Authorized
in
mercis
1/8/24

1/5 \$ 2100
4 days

Estimate

PAGE : 1/3

YEAR : _____ VEHICLE NO : SMZ5823T
MODEL : HONDA CIVIC CHASSIS NO : MRHFC5650KT000586

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Tail lamp n/s 340.50 cm	1	\$2,200.00 ✓
2	Rear bumper 617.20 Dis	1	\$1,350.00 ✓
3	Rear bumper side retainer n/s 45.00 cm	1	\$168.00 ✓
4	Rear bumper reflector n/s	1	\$220.00 X
5	Rear bumper reflector garnish n/s 48.60 Dis	1	\$280.00 ✓
6	Rear bumper lower garnish 109.20 De	1	\$288.00 ✓
7	End panel	1	\$980.00 X
8	End panel top trim	1	\$165.00 X
9	End panel inner garnish	1	\$220.00 X
10	Exhaust	1	\$1,200.00 X
11	Rear floor panel side board	2	\$330.00 X
12	Rear fender inner trim	2	\$1,240.00 X
13	Rear fender inner shield n/s 166.80 Tra	1	\$230.00 ✓
14			
15			
16			\$8,871.00
17		Discount 20%	\$1,774.20
18		TOTAL :	\$7,096.80
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			

Estimate

PAGE : 2/3

YEAR : _____ VEHICLE NO : SMZ5823T
MODEL : HONDA CIVIC CHASSIS NO : MRHFC5650KT000586

S/NO	S/N ITEMS	Qty	Price
1	Rear bumper clips <i>new</i>	1 set	\$50.00 <i>30 \$/w</i>
2	End panel sealant <i>11</i>	1	\$80.00 <i>X</i>
3	End panel top trim clip <i>11</i>	1	\$50.00 <i>X</i>
4	Rear fender inner trim clip <i>11</i>	1	\$50.00 <i>X</i>
5	Rear fender inner shield clip <i>11</i>	1	\$50.00 <i>X</i>
6	Reverse sensor <i>malfunction</i>	1 set	\$280.00 <i>200 \$/w</i>
			\$560.00
Parts Total :			\$0.00
S/P Item :			\$560.00
TOTAL :			\$560.00

3 MOTORWERKZ CONCEPT PTE LTD

Estimate

PAGE : 3/3

YEAR : _____ VEHICLE NO : SMZ5823T
 MODEL : HONDA CIVIC CHASSIS NO : MRHFC5650KT000586

S/NO	LABOURS	AMOUNT
1	To straighten and panel beat rear frame members, to cut/weld rear portion to remove and refit above parts. 550	\$ 1,000.00
2	To putty, re-spray painting and polish rear affected areas. 700	\$ 1,000.00
3	To rust proof affected rear areas. 17 X	\$ 200.00
4	To remove and install carpet, trim and interior 60	\$ 200.00
5	To remove, install and check reverse sensor 30	\$ 100.00
6	To conduct disgnotic. 17 X	

TOTAL : \$ 2,500.00

PARTS TOTAL : \$ 560.00

GRAND TOTAL : \$ 3,060.00

10156.80

Insurance Consultants hence notify
 the insurer of the following:
 1. To survey before/after survey
 2. To display damaged part(s) during resurvey
 3. Parts prices are subject to confirmation
 4. Third party survey is on a "Without Prejudice" basis
 5. No illegal modification(s) is allowed
 6. Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

P-132730
 206
1061.84
 230
 1340
2631.84
 206
 2105