

ASS. REC. BY:

REF:

SMR/

CS/SMR24080010/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/IMV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

03/29

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJZ 19517

Yr Regn:

06, 92

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Civic

C.C

1595

Colour

D. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

415735

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMEG83900S 0003782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/508R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/7/24

D.O.I.

1/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2018 21 Sep @ 5:50. Colm (Red. \$ 9497.44, 64%)

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
 Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
 Business Registration No. 201312846W
 GST Registration No. 201312846W

*Not Notified
 11 Pm @ 5150h
 Runny After Rain
 5 days*

ESTIMATE

Date: 31/7/2024
 DOA: 27/7/2024

Vehicle No: SJZ1951T
 Make & Model: Honda Civic EK9

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Bumper <i>638</i>	\$ 1,348.50	<i>Bu</i>
2	1	Rear Bumper Side Retainer	\$ 251.50	<i>R</i>
3	2	Rear Bumper Parking Sensor	\$ <i>Sm</i> 519.00	<i>X</i>
4	2	Rear Tail Lamp	\$ <i>olsem</i> 25.30	<i>X</i>
5	2	Rear Tail Gate Tail Lamp	\$ <i>Sm</i> 128.40	<i>X</i>
			\$ 2,372.70	
		Less 20%	\$ 474.54	
			\$ 1,898.16	
Special Nett Items				
1		Sundries	\$ <i>nn</i> 50.00	<i>X</i>
2	1	Rear Carbon Fibre Tail Gate <i>2150</i>	\$ 3,000.00	<i>CPM</i>
3	1 set	Rear Bumper Clips	\$ <i>nn</i> 50.00	<i>nn</i>
4	1 set	Rear No. Plate with Garnish	\$ <i>nn</i> 150.00	<i>X</i> <i>2512</i>
5	1 set	Rear Reverse Camera	\$ <i>Sm</i> 300.00	<i>X</i>
6	1	Rear Exhaust Assembly <i>Pr: 1800</i>	\$ <i>nn</i> 4,500.00	<i>X</i>
	1 set	Rear Reverse Sensor <i>- \$300 X</i> <i>svc</i>	\$ 8,050.00	
		Total Parts	\$ 9,948.16	
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.		\$ 1,600.00	<i>500</i>
2	To putty and spray painting rear portion.		\$ 1,200.00	<i>400</i>
3	To check rear lighting and wiring.		\$ 80.00	<i>201</i>
4	To remove and install rear tail gate lock mechanism.		\$ 120.00	<i>501</i>
5	To apply anti rust proofing to rear affected area.		\$ 250.00	<i>X</i>
6	To remove and install rear reverse camera.		\$ 150.00	<i>301</i>
7	To remove and install rear reverse sensor.		\$ 150.00	<i>501</i>
8	To remove & refit tail gate component to replace tail gate, check & re-adjust the close gap and alignment and water seepage		\$ <i>nn</i> 120.00	<i>X</i>
	Total labour :		\$ 3,670.00	
	Total parts :		\$ 9,948.16	
	Total labour :		\$ 3,670.00	
	Total repair cost :(Before GST)		\$ 13,618.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14647.44

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

ESTIMATE

Date: 31/7/2024
DOA: 27/7/2024

Vehicle No: SJZ1951T

Make & Model: Honda Civic EK9

S/N	Qty	Item Description	Parts Price	Surveyor
		Supplementary Items		
1	1	Rear End Panel <i>481</i>	\$ 698.40	<i>By</i>
2	2	Rear Tail Gate Side Lock Mechanism <i>o/s new</i>	\$ 588.20	<i>LF</i>
			\$ 1,286.60	
		Less 20%	\$ 257.32	
			\$ 1,029.28	