

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg

Business Registration No. 201312846W

GST Registration No. 201312846W

*Not Not heist
11 Pm @ 5150h
Rummy After Pain
5 days*

ESTIMATE

Date: 31/7/2024
DOA: 27/7/2024

Vehicle No: SJZ1951T
Make & Model: Honda Civic EK9

Vehicle No: S3219511			Parts Price		Surveyor
Make & Model: Honda Civic EK9					
S/N	Qty	Item Description			
1	1	Rear Bumper	638	\$ 1,348.50	
2	1	Rear Bumper Side Retainer		\$ 251.50	x
3	2	Rear Bumper Parking Sensor		\$ 519.00	x
4	2	Rear Tail Lamp		\$ 25.30	4 312.63
5	2	Rear Tail Gate Tail Lamp		\$ 128.40	x
				\$ 2,372.70	
				\$ 474.54	
		Less 20%		\$ 1,898.16	
Special Nett Items					
1		Sundries		\$ 50.00	x
2	1	Rear Carbon Fibre Tail Gate	2150	\$ 3,000.00	—
3	1 set	Rear Bumper Clips		\$ 50.00	—
4	1 set	Rear No. Plate with Garnish		\$ 150.00	* 250
5	1 set	Rear Reverse Camera		\$ 300.00	x
6	1	Rear Exhaust Assembly	1100 1800	\$ 4,500.00	x
	1 set	Rear Reverse Sensor	- \$300 x	\$ 8,050.00	
				\$ 9,948.16	
Total Parts					
S/N	Labour Description	Amount	Amount		
1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.	\$ 1,600.00	500		
2	To putty and spray painting rear portion.	\$ 1,200.00	400		
3	To check rear lighting and wiring.	\$ 80.00	20		
4	To remove and install rear tail gate lock mechanism.	\$ 120.00	50		
5	To apply anti rust proofing to rear affected area.	\$ 250.00	x		
6	To remove and install rear reverse camera.	\$ 150.00	30		
7	To remove and install rear reverse sensor.	\$ 150.00	50		
8	To remove & refit tail gate component to replace tail gate, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	x		
	Total labour :	\$ 3,670.00			
	Total parts :	\$ 9,948.16			
	Total labour :	\$ 3,670.00			
	Total repair cost : (Before GST)	\$ 13,618.16			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

ESTIMATE

Date: 31/7/2024
DOA: 27/7/2024

Vehicle No: SJZ1951T

Make & Model: Honda Civic EK9

S/N	Qty	Item Description	Parts Price	Surveyor
		<u>Supplementary Items</u>		
1	1	Rear End Panel 481 By	\$ 698.40	✓
2	2	Rear Tail Gate Side Lock Mechanism o/s nd	\$ 588.20	✓
			\$ 1,286.60	
		Less 20%	\$ 257.32	
			\$ 1,029.28	