

**MCR MOTORS PTE.LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-53 SINGAPORE 415875

Vehicle number: SMF2333R

Make &amp; Model: Nissan GT-R

Chassis number: JN1GANR35U0102123

| No. | Description of spare parts         | Qty  | Amount S\$     |
|-----|------------------------------------|------|----------------|
| 1   | Bootlid X nn                       | 1    | \$ 6,530.00    |
| 2   | Bootlid lock X nn                  | 1    | \$ 395.00      |
| 3   | Bootlid weatherstrip X nn          | 1    | \$ 442.00      |
| 4   | Rear bumper / BR                   | 1    | \$ 4,116.00    |
| 5   | Rear bumper clips / n/c            | 1set | \$ 50 / 120.00 |
| 6   | Rear bumper "GTR" emblem / n/c     | 1    | \$ 283.10      |
| 7   | Rear bumper lower garnish / CRA    | 1    | \$ 1,538.00    |
| 8   | Rear bumper RH side retainer / BR  | 1    | \$ 211.20      |
| 9   | Rear bumper LH side retainer / BR  | 1    | \$ 211.20      |
| 10  | Rear bumper reinforcement / OT     | 1    | \$ 1,455.00    |
| 11  | RH taillamp assy X nn              | 1    | \$ 2,048.60    |
| 12  | RH taillamp panel X nn             | 1    | \$ 499.60      |
| 13  | RH taillamp lock clips X nn        | 1set | \$ 80.00       |
| 14  | LH taillamp assy X nn              | 1    | \$ 2,048.60    |
| 15  | LH taillamp panel X nn             | 1    | \$ 499.60      |
| 16  | LH taillamp lock clips X nn        | 1set | \$ 80.00       |
| 17  | End panel X R                      | 1    | \$ 1,189.00    |
| 18  | End panel inner garnish X nn       | 1    | \$ 405.30      |
| 19  | End panel inner garnish clips X nn | 1set | \$ 80.00       |

\$ 22,232.20  
 Parts less 10% \$ 2,223.22  
 Total: \$ 20,008.98

| No. | Special Nett Items                             | Qty  | Amount S\$      |
|-----|------------------------------------------------|------|-----------------|
| 1   | Rear bumper lower diffuser (after market) / BR | 1    | \$ 2,800.00     |
| 2   | Rear bumper lower diffuser red sticker / n/c   | 1    | \$ 200 / 320.00 |
| 3   | Rear bumper RH lower spoiler X nn              | 1    | \$ 1,900.00     |
| 4   | Rear bumper RH lower spoiler red sticker / n/c | 1    | \$ 80 / 240.00  |
| 5   | Rear bumper LH lower spoiler X nn              | 1    | \$ 1,900.00     |
| 6   | Rear bumper LH lower spoiler red sticker / n/c | 1    | \$ 80 / 240.00  |
| 7   | Rear bumper reverse sensor / Defused           | 1set | \$ 300 / 380.00 |
| 8   | Exhaust silencer RH (after market) X nn        | 1    | \$ 5,600.00     |

|    |                                                |   |             |
|----|------------------------------------------------|---|-------------|
| 9  | Exhaust silencer gasket RH (after market) × nn | 1 | \$ 180.00   |
| 10 | Exhaust silencer LH (after market) × nn        | 1 | \$ 5,600.00 |
| 11 | Exhaust silencer gasket LH (after market) × nn | 1 | \$ 180.00   |
| 12 | Rear number plate X nn                         | 1 | \$ 80.00    |
|    |                                                |   |             |
|    |                                                |   |             |

Total: \$ 19,420.00 1,660

| No. | Labour and painting                                                      | Amount S\$  |
|-----|--------------------------------------------------------------------------|-------------|
|     |                                                                          |             |
| 1   | Labour charges to the affected and consistent areas                      | \$ 2,000.00 |
| 2   | Spray painting on affected and consistent areas and panels               | \$ 1,700.00 |
| 3   | Check wiring and lighting system on affected areas                       | \$ 100.00   |
| 4   | Apply rust coating chemical on affected areas and panels                 | \$ 120.00   |
| 5   | Remove and replace bootlid inner mechanism to new bootlid                | \$ 180.00   |
| 6   | Remove and replace rear bumper reverse sensors to assist repair          | \$ 150.00   |
| 7   | Remove and replace rear inner garnish, trims and boards to assist repair | \$ 450.00   |
| 8   | Remove and replace exhaust silencers and gaskets to assist repair        | \$ 500.00   |
|     |                                                                          |             |
|     |                                                                          |             |

Total labour \$ 5,200.00 940

Steve (LKK)

13/6/24, 8.30pm

W R

L/S

My AC My

4 3 d/s

Total: \$ 44,628.98

9,181.61

L/S - 7,345.28  
= 7350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: