

MCR MOTORS PTE.LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-53 SINGAPORE 415875

Vehicle number: SMF2333R

Make & Model: Nissan GT-R

Chassis number: JN1GANR35U0102123

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid ✓	1	\$ 6,530.00
2	Bootlid lock ✓	1	\$ 395.00
3	Bootlid weatherstrip ✓	1	\$ 442.00
4	Rear bumper / BR	1	\$ 4,116.00
5	Rear bumper clips / APC	1set	\$ 50 120.00
6	Rear bumper "GTR" emblem / APC	1	\$ 283.10
7	Rear bumper lower garnish / CRA	1	\$ 1,538.00
8	Rear bumper RH side retainer / BR	1	\$ 211.20
9	Rear bumper LH side retainer / BR	1	\$ 211.20
10	Rear bumper reinforcement / OT	1	\$ 1,455.00
11	RH taillamp assy ✓	1	\$ 2,048.60
12	RH taillamp panel ✓	1	\$ 499.60
13	RH taillamp lock clips ✓	1set	\$ 80.00
14	LH taillamp assy ✓	1	\$ 2,048.60
15	LH taillamp panel ✓	1	\$ 499.60
16	LH taillamp lock clips ✓	1set	\$ 80.00
17	End panel ✓ R	1	\$ 1,189.00
18	End panel inner garnish ✓	1	\$ 405.30
19	End panel inner garnish clips ✓	1set	\$ 80.00
			\$ 22,232.20
		Parts less 10%	\$ 2,223.22
		Total:	\$ 20,008.98

No.	Special Nett Items	Qty	Amount S\$
1	Rear bumper lower diffuser (after market) / BR	1	\$ 2,800.00
2	Rear bumper lower diffuser red sticker / APC	1	\$ 200 320.00
3	Rear bumper RH lower spoiler ✓	1	\$ 1,900.00
4	Rear bumper RH lower spoiler red sticker / APC	1	\$ 80 240.00
5	Rear bumper LH lower spoiler ✓	1	\$ 1,900.00
6	Rear bumper LH lower spoiler red sticker / OT	1	\$ 80 240.00
7	Rear bumper reverse sensor / Defused	1set	\$ 300 380.00
8	Exhaust silencer RH (after market) ✓	1	\$ 5,600.00

9	Exhaust silencer gasket RH (after market) ✕	1	\$ 180.00
10	Exhaust silencer LH (after market) ✓	1	\$ 5,600.00
11	Exhaust silencer gasket LH (after market) ✕	1	\$ 180.00
12	Rear number plate ✕	1	\$ 80.00

Total: \$ 19,420.00

No.	Labour and painting	Amount S\$
1	Labour charges to the affected and consistent areas	\$ 2,000.00
2	Spray painting on affected and consistent areas and panels	\$ 1,700.00
3	Check wiring and lighting system on affected areas	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Remove and replace bootlid inner mechanism to new bootlid	\$ 180.00
6	Remove and replace rear bumper reverse sensors to assist repair	\$ 150.00
7	Remove and replace rear inner garnish, trims and boards to assist repair	\$ 450.00
8	Remove and replace exhaust silencers and gaskets to assist repair	\$ 500.00

Total labour \$ 5,200.00

Steve (LKK)

13/6/24, 1.30pm

W R

L/S

My AC My

4 3 d/s

Total: \$ 44,628.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: