

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3154/07/24

Your Ref:

LKK Auto Consultants hence notify the Repairer of the following:

Date: 31st July 2024

The Claim's Manager
Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Chua Hood Kiat, Anthony

Date Of Accident : 30/07/24 (12:30hrs)

Policy Number : D20MFC0005258_03

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repair to MAZDA CX-3 (A) 2.0 SUV - SBX 72 S

1 pc rear bumper	cur/70.1		\$ 1,193.15
10 pcs rear bumper clips	nei	© \$ 5.71	57.10
1 pc rear bumper o/s top retainer	cm		26.30
1 pc rear bumper o/s side retainer	cm		26.81
1 pc rear bumper centre lower garnish	gnd		148.87
1 pc rear bumper o/s reflector	17		174.81
1 set rear bumper reverse sensor	sel		369.18
1 pc o/s tail lamp assy LED	cm (MDM 4N-51-150A)	1650.02	2,192.62
2 pcs o/s tail lamp clips stopper	17	© \$ 5.71	11.42
1 pc rear o/s fender	5025.00/5uc		1,242.88
6 pcs rear o/s fender inner shield clips	nei	© \$ 5.71	34.26
1 pc rear o/s fender quarter glass seal	nei		36.71
1 pc rear o/s fender quarter glass inner demper	nei		39.61
1 pc rear o/s fender quarter glass sealant	nei		60.00
1 pc rear o/s wheel guard garnish	2.5 nei		86.67
10 pcs rear o/s wheel garnish clips & stopper	© \$ 5.71 17		57.10
1 pc rear o/s wheel garnish bracket	nei		37.17
1 pc rear o/s sport rim	n		821.71
	6616.37		\$ 6,615.71
	Less 20%		\$ 1,323.14
			\$ 5,292.57

To wiring check up for affected wiring system.	50.00	20
To remove & refix rear o/s fender quarter glass & necessary,	150.00	60
To remove & refix cushion seat, carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts.	180.00	80
To check & adjust wheel alignment & balancing.	150.00	60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.	1,250.00	800
To putty & respray painting on all affected accident parts.	1,350.00	600
	8423.09	
	\$ 8,422.57	

Dollars : Eight Thousand Four Hundred Twenty Two And Cents Fifty Seven Only.

HUP MOTOR TRADING & SERVICE

1- 4579.55
202
3663.64
30
1620
5313.64

Not Addressed
2/8/24
Excess ? 750?
1/5 # 4200
Tele ph. Abt rep.
5-days