

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3154/07/24

Your Ref:

LKK Auto Consultants hence notify the Repairer of the following:

Date: 31st July 2024

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not Affected
2/8/24
Excess 750?
1/5 #3800
Tele the HUP rep.
5-days

The Claim's Manager
Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Chua Hood Kiat, Anthony

Date Of Accident : 30/07/24 (12:30hrs)

Policy Number : D20MPC0005258_03

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repair to MAZDA CX-3 (A) 2.0 SUV - SBX 72 S

1 pc rear bumper	cut to 1	
10 pcs rear bumper clips	new	© \$ 5.71
1 pc rear bumper o/s top retainer	cm	
1 pc rear bumper o/s side retainer	cm	
1 pc rear bumper centre lower garnish	garnish	
1 pc rear bumper o/s reflector	17	
1 set rear bumper reverse sensor	SW	
1 pc o/s tail lamp assy	cm (MDM 4N-51-150A)	956.34
2 pcs o/s tail lamp clips stopper	17	© \$ 5.71
1 pc rear o/s fender	5025.00/150C	
6 pcs rear o/s fender inner shield clips	new	© \$ 5.71
1 pc rear o/s fender quarter glass seal	new	
1 pc rear o/s fender quarter glass inner demper	new	
1 pc rear o/s fender quarter glass sealant	2.1 new	
1 pc rear o/s wheel guard garnish		
10 pcs rear o/s wheel garnish clips & stopper		© \$ 5.71 17
1 pc rear o/s wheel garnish bracket	new	
1 pc rear o/s sport rim	new	

\$ 1,193.15	—
57.10	—
26.30	—
26.81	—
148.87	—
174.81	X
369.18	X
2,192.62	—
11.42	X
1,242.88	—
34.26	—
36.71	—
39.61	—
60.00	30 SW
86.67	—
57.10	X
37.17	—
821.71	X

6616.37

Less 20%

\$ 6,615.71
\$ 1,323.14
\$ 5,292.57

To wiring check up for affected wiring system.	50.00	70
To remove & refix rear o/s fender quarter glass & necessary,	150.00	60
To remove & refix cushion seat, carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts.	180.00	80
To check & adjust wheel alignment & balancing.	150.00	60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.	1,250.00	800
To putty & respray painting on all affected accident parts.	1,350.00	600
	8423.09	
	\$ 8,422.57	

Dollars : Eight Thousand Four Hundred Twenty Two And Cents Fifty Seven Only.

HUP MOTOR TRADING & SERVICE

1-388587
202
3108.69
30
1620