

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd  
6 Raffles Quay  
#22-00  
Singapore 048580From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sherini Pillai

Date: 05 Aug 2024

**Preliminary Advice**

Vehicle No	: SBX72S	Accident Date	: 30/07/2024
Make	: MAZDA CX-3	Policy No.	: D20MPC0005258
Assignment Date	: 01/08/2024	Excess	: S\$0.00
Date of Inspection	: 02/08/2024	Est. Duration of Repair	: 5
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,423.09
Revised Amount	:S\$	5,747.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,747.72
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	28,312.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,688.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.