

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road

Springleaf Tower #16-00

Singapore 079909

Tel: 63896111

Fax: 6221033

Attn: Motor Claim Department

Your Ref No: TP 0724-8164

Claim Type: Third Party

Accident Date: 31 July 2024

TP Veh Reg No: SLW9754K

Estimate No: EST1511591

Date: 31 Jul 2024

Policy No: MT/00859097/03

Veh Reg No: SFF8772A

Make/Model: TOYOTA NOAH 2.0S A

Chassis No: ZRR700146521

Engine No: 3ZR4199321

Reg. Date: 20 Oct 2008

not available
moras
12/8/24
2/5 \$4300
4 days
the phone array -

Estimate Repair Cost to Vehicle No: SFF8772A

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER <i>DD/De</i>	1,080.60	1 PC	1,080.60	—
2 REAR BUMPER SIDE RETAINER (INNER) - LH/RH <i>17</i>	108.60	2 PC	217.20	X
3 REAR BUMPER SIDE RETAINER (OUTER) - LH/RH <i>17</i>	98.70	2 PC	197.40	X
4 REAR BUMPER CLIPS <i>1er</i>	5.50	10 PC	55.00	—
5 REAR BUMPER REFLECTOR - LH/RH <i>11</i>	80.60	2 PC	161.20	X
6 REAR BUMPER TOW COVER <i>17</i>	40.60	1 PC	40.60	X
7 TAILGATE <i>DD/De</i>	2,875.60	1 PC	2,875.60	—
8 TAILGATE TOYOTA LOGO <i>1er</i>	72.50	1 PC	72.50	—
9 TAILGATE OUTER CHROME <i>1er</i>	850.40	1 PC	850.40	X
10 TAILGATE "S" WORDINGS <i>1er</i>	71.50	1 PC	71.50	—
11 TAILGATE GLASS MOULDING <i>1er</i> <i>211.50</i>	380.60	1 PC	380.60	—
12 TAILGATE WEATHERSTRIP <i>11</i>	480.40	1 PC	480.40	X
13 TAILGATE TOP LOCK <i>SVC</i>	560.00	1 PC	560.00	X
14 REAR END PANEL (OUTER) <i>DD/De</i>	688.40	1 PC	688.40	—
15 REAR END PANEL TOP GARNISH <i>17</i>	380.40	1 PC	380.40	X
16 REAR END PANEL TOP GARNISH SMALL LOCK COVER <i>17</i>	60.50	1 PC	60.50	X
			8,172.30	
			Less 25%	-2,042.90
				6,129.40
Special Net				
17 SEALANT <i>Rear window screen</i>	20.00	2 PC	<i>1er</i> 40.00	—
18 SPONGE TAPE <i>Rear window screen</i>	20.00	1 PC	<i>1er</i> 20.00	—
19 REAR BUMPER SENSOR <i>SW</i>	200.00	1 PC	200.00	X
				260.00
Labour				
20 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	800.00	1 JOB	800.00	600
21 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	800.00	1 JOB	800.00	600
22 TO CHECK WIRING- <i>refy</i>	30.00	1 JOB	30.00	30
23 TO REMOVE, REPLACE REAR BUMPER SENSOR-	150.00	1 JOB	150.00	30
24 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	80.00	1 JOB	80.00	60
25 TO TRANSFER TAILGATE FITTINGS-	80.00	1 JOB	80.00	50
26 TO TUFFKOTE-	90.00	1 JOB	90.00	50
27 TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	120
				2,180.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	8,569.40
Add GST @ 9%	771.25
Total Amount Payable SGD	9,340.65

SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED FORTY AND CENTS SIXTY FIVE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5052-4
262
3791.55
1387.58

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE