

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/24080014/Unp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFF 8772A

at Workshop m/s PA ubi 320.

of _____

Insured: SLW 9784K

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$40K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA \$13614
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFF 8772A Yr Regn: 20/12/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Noah c.c. 1988

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 337807 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZRR 700146521

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MCG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/07/24 D.O.I. 12/08/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rep #17. 10K.

20/8/24 Cope with 19-10-2028
4/5 & 4300 Inland Roy
(Red. \$4269.4 / 49%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

Tel: 63896111

Fax: 6221033

Attn: Motor Claim Department

Your Ref No: TP 0724-8164

Claim Type: Third Party

Accident Date: 31 July 2024

TP Veh Reg No: SLW9754K

Estimate No:

EST1511591

Date:

31 Jul 2024

Policy No:

MT/00859097/03

Veh Reg No:

SFF8772A

Make/Model:

TOYOTA NOAH 2.0S A

Chassis No:

ZRR700146521

Engine No:

3ZR4199321

Reg. Date:

20 Oct 2008

Estimate Repair Cost to Vehicle No: SFF8772A

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER <i>DD/De</i>	1,080.60	1 PC	1,080.60	—
2 REAR BUMPER SIDE RETAINER (INNER) - LH/RH <i>17</i>	108.60	2 PC	217.20	X
3 REAR BUMPER SIDE RETAINER (OUTER) - LH/RH <i>17</i>	98.70	2 PC	197.40	X
4 REAR BUMPER CLIPS <i>121</i>	5.50	10 PC	55.00	—
5 REAR BUMPER REFLECTOR - LH/RH <i>17</i>	80.60	2 PC	161.20	X
6 REAR BUMPER TOW COVER <i>17</i>	40.60	1 PC	40.60	X
7 TAILGATE <i>DD/De</i>	2,875.60	1 PC	2,875.60	—
8 TAILGATE TOYOTA LOGO <i>121</i>	72.50	1 PC	72.50	—
9 TAILGATE OUTER CHROME <i>17</i>	850.40	1 PC	850.40	X
10 TAILGATE "S" WORDINGS <i>121</i>	71.50	1 PC	71.50	—
11 TAILGATE GLASS MOULDING <i>121</i> <i>211.50</i>	380.60	1 PC	380.60	—
12 TAILGATE WEATHERSTRIP <i>17</i>	480.40	1 PC	480.40	X
13 TAILGATE TOP LOCK <i>SVC</i>	560.00	1 PC	560.00	X
14 REAR END PANEL (OUTER) <i>DD/De</i>	688.40	1 PC	688.40	—
15 REAR END PANEL TOP GARNISH <i>17</i>	380.40	1 PC	380.40	X
16 REAR END PANEL TOP GARNISH SMALL LOCK <i>17</i>	60.50	1 PC	60.50	X
COVER				
			8,172.30	
		Less 25%	-2,042.90	6,129.40
Special Net				
17 SEALANT <i>Reer wind screen</i>	20.00	2 PC	<i>121</i> 40.00	—
18 SPONGE TAPE <i>Reer wind screen</i>	20.00	1 PC	<i>121</i> 20.00	—
19 REAR BUMPER SENSOR <i>SVC</i>	200.00	1 PC	200.00	X
				260.00
Labour				
20 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	800.00	1 JOB	800.00	600
21 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	800.00	1 JOB	800.00	600
22 TO CHECK WIRING- <i>refy</i>	30.00	1 JOB	30.00	30
23 TO REMOVE, REPLACE REAR BUMPER SENSOR-	150.00	1 JOB	150.00	30
24 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	80.00	1 JOB	80.00	60
25 TO TRANSFER TAILGATE FITTINGS-	80.00	1 JOB	80.00	50
26 TO TUFFKOTE-	90.00	1 JOB	90.00	50
27 TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	120
				2,180.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	8,569.40
Add GST @ 9%	771.25
Total Amount Payable SGD	9,340.65

SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED FORTY AND CENTS SIXTY FIVE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5052-4
262
3791.55
5381.58

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE