

Quotation

DATE: 29/7/2024
 VEHICLE NO: PC1973E
 DRIVER: RAYMOND SOH SAY CHIAN
 TYPE OF CLAIM: CLAIM 3RD PARTY
 PREPARED BY: MUSTAPA

LOCATION: Gul Workshop
 Q REF No:
 DEPARTMENT: AIRPORT BUS
 ACCIDENT DATE: 26/7/2024
 REF No: JW/0724/291

S/N	Description	Qty	Cost per Unit	Total cost W/O Gst
SPARE PARTS				
1	DOOR HINGES <i>bt</i>	2	133	266.00
2	LIVERY STICKER <i>rec</i>	1	1050	1,050.00
3	STICKER 60KM/H <i>rec</i>	1	15	15.00
4	STICKER EMERGENCY DOOR <i>rec</i>	1	10	10.00
LABOUR				
1	TO REMOVE & REPLACE BOTH REAR DOOR HINGES.	1	150	150.00
2	TO ADJUST & RE ALIGN REAR BUMPER & REAR DOOR	1	200	200.00
3	TO REPAIR, PANEL BEAT, PUTTY & SMOOTHEN L/H/R SIDE PANEL, REAR BUMPER & REAR DOOR ACCIDENT AREA	1	1200	1,200.00
SPRAY PAINTING				
1				
Total Amount				2891.00

266
 108
 239.40
 1075
 1100

Total cost subjected to GST
 Remarks: LOU 4 DAYS

Mustapa 1/8/24
 Signature of Workshop

Thomas 1/8/2024
 Signature of Department Head

Signature of Claim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

239.40
 1075.00
 1100.00
 2414.40
Rahul
 Hp 900 10568
 4 days
 06/08/24
 Reg after repair