

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 01/08/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J028363	2ZR0B89973	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SHF92H ACC DATE:31/07/2024 DRIVE IN:01/08/2024 DATE-IN:01/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	S	BP-SUBLET REAR NUMBER PLATE				- 80.00
3	S	BP-SUBLET PHV STICKER				- 20.80
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				- 198.00
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				- 198.00
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				- 594.00
7	B	BP-LAB2 REPLACE & INSTALL REAR TAILGATE GLASS				- 594.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				200 100 200.00
9	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				- 396.00
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				- 198.00
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				3168 2376 3960.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



ndcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 01/08/2024	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J028363	2ZR0B89973	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS			3280	2624	3280.00
13	1	TREVSE-47006 24 BACK SENSOR 1G3 GREY ME <i>MIS</i>	1.00	101.05			101.05
14	2	U52159-47912 COVER, RR BUMPER <i>1.00 Xan</i>	1.00	855.40			855.40
15	3	U52576-47030 RETAINER, RR BUMPER <i>1.00 Xan</i>	1.00	89.90			89.90
16	4	U52156-47010 SUPPORT, RR BUMPER <i>1.00 Xan</i>	1.00	217.70			217.70
17	5	U52575-47030 RETAINER, RR BUMPER <i>1.00 Xan</i>	1.00	89.90			89.90
18	6	U52155-47010 SUPPORT, RR BUMPER <i>1.00 Xan</i>	1.00	217.70			217.70
19	7	K52161-0K040 PIECE, RR BUMPER <i>10.00</i>	10.00	5.80			58.00
20	8	U52023-12240 REINFORCEMENT <i>1.00</i>	1.00	334.00			334.00
21	9	U52016-47060 ARM SUB-ASSY, RR <i>1.00</i>	1.00	243.00			243.00
22	0	U52015-47080 ARM SUB-ASSY, RR <i>1.00</i>	1.00	243.00			243.00
23	1	U52023-12240 REINFORCEMENT <i>1.00</i>	1.00	334.00			334.00
24	2	U52016-47060 ARM SUB-ASSY, RR <i>1.00</i>	1.00	243.00			243.00
25	3	U52015-47080 ARM SUB-ASSY, RR <i>1.00</i>	1.00	243.00			243.00
26	4	U76891-47040 SPOILER, RR NO.1 <i>1.00</i>	1.00	1175.80			1175.80
27	5	U75392-35220 RETAINER, OUTSIDE <i>10.00</i>	10.00	5.60			56.00
28	6	U81910-47010 REFLECTOR ASSY, <i>1.00</i>	1.00	83.40			83.40
29	7	U52591-47030 SEAL, RR BUMPER <i>1.00</i>	1.00	124.60			124.60
30	8	U58307-47080 PANEL SUB-ASSY, BODY <i>1.00</i>	1.00	1058.90			1058.90
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary		Total		
		Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

inciscope
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498
	Document No. 0	Work: 65703925
	Document Date 01/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J028363	2ZR0B89973	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	9	U58308-47030 COVER SUB-ASSY, RR <i>? car</i>	1.00	757.90		✓ 757.90
32	0	U67935-47010 CO PLATE, BACK DOOR <i>? xsv</i>	1.00	251.40		✓ 251.40
33	1	U67005-47460 PANEL SUB-ASSY, BACK <i>bt</i>	1.00	1692.80		✓ 1692.80
34	2	U67881-47030 WEATHERSTRIP, BACK <i>cut</i>	1.00	463.80		✓ 463.80
35	3	U68105-47170 GLASS SUB-ASSY, BACK <i>as photo</i>	1.00	1675.30		✓ 1675.30
36	4	U56117-50140 DAM, WINDOW GLASS <i>as</i>	1.00	40.10		✓ 40.10
37	5	T69350-28151 LOCK ASSY, BACK DOOR <i>? xsv</i>	1.00	571.50		✓ 571.50
38	6	U75310-47020 EMBLEM ASSY, <i>as</i>	1.00	87.90		✓ 87.90
39	7	U75442-47080 PLATE, BACK DOOR <i>as</i>	1.00	87.90		✓ 87.90
40	8	U75441-47130 PLATE, LUGGAGE COMPT <i>as</i>	1.00	75.70		✓ 75.70
41	9	U81561-47252 LENS & BODY, RR <i>xsv</i>	1.00	1022.70		✓ 1022.70
42	0	U81551-47262 LENS & BODY, RR <i>as</i>	1.00	1069.50		✓ 1069.50
43	1	U81551-47262 LENS & BODY, RR <i>xsv</i>	1.00	1069.50		✓ 1069.50
44	2	T81496-21010 GUIDE, RR <i>as</i>	2.00	5.00		✓ 10.00
45	3	U89997-30070 ANTENNA, ELECTRICAL <i>? xsv</i>	1.00	266.20		✓ 266.20
46	4	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>as</i>	2.00	108.00		✓ 216.00
47	5	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>as</i>	1.00	200.00		✓ 200.00

For & on behalf of Borneo Motors	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Customer's Signature	Charge Summary	Total	25,145.35
		Please acknowledge receipt of vehicle	Parts 15,326.55	GST 9.00%	2,263.08
			Labour 9,718.00		
			Sublet 100.80		
			Lubrication/Fluid 0.00	Less	0.00
			Others 0.00	Amount Due	27,408.43

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 10/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU80J028363		2ZR0B89973	60	Sam San Joi	02/08/2024 8.00		12/08/2024 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	B	BP-MECH2 REPLACE & INSTALL REAR EXHAUT PIEP ASSY ✓ BP64						792.00
2	1	U17430-37480 PIPE ASSY, EXHAUST ✓			1.00	1153.00		1153.00
3	2	U17410-37572 PIPE ASSY, EXHAUST, ✓			1.00	7767.80		7767.80
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						9,712.80		
		Please acknowledge receipt of vehicle		Parts 8,920.80		GST 9.00% 874.15		
				Labour 792.00				
				Sublet 0.00				
				Lubrication/Fluid 0.00		Less		
				Others 0.00		0.00		
						Amount Due 10,586.95		

Customer Copy