



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept				S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 10/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDZS3EU80J028363		2ZR0B89973	60	Sam San Joi	02/08/2024	8.00	12/08/2024	18.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SHF92H ACC DATE:31/07/2024 DRIVE IN:01/08/2024 DATE-IN:01/08/2024 DATE SURVEY:02/08/2024 NO OF REPAIR DAYS:11 DAYS BY:RASUL(LKK)							50.00
2	S	BP-SUBLET REAR NUMBER PLATE				0263			80.00
3	S	BP-SUBLET PHV STICKER				0575			20.80
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				*			198.00
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				*			198.00
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				*			594.00
7	B	BP-LAB2 REPLACE & INSTALL REAR TAILGATE GLASS				*			594.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)							200.00
9	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				*			396.00
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				BP64			198.00
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				*			3168.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature			Charge Summary			Total
			Please acknowledge receipt of vehicle			Parts Labour Sublet Lubrication/Fluid Others			
									Less
									Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 10/10/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J028363	2ZR0B89973	60	Sam San Joi	02/08/2024 8.00	12/08/2024 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS *				3280.00
13	B	BP-MECH2 REPLACE & INSTALL REAR EXHAUT PIEP ASSY BP64				792.00
14	1	TREVSE-47006 23 BACK SENSOR 1F7 SILVER ME	1.00	101.05		101.05
15	2	U52159-47912 COVER, RR BUMPER	1.00	855.40		855.40
16	3	U52156-47010 SUPPORT, RR BUMPER	1.00	217.70		217.70
17	4	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
18	5	U52023-12240 REINFORCEMENT	1.00	334.00		334.00
19	6	U52015-47080 ARM SUB-ASSY, RR	1.00	243.00		243.00
20	7	U76891-47040 SPOILER, RR NO.1	1.00	1175.80		1175.80
21	8	U81910-47010 REFLECTOR ASSY,	1.00	83.40		83.40
22	9	U52591-47030 SEAL, RR BUMPER	1.00	124.60		124.60
23	0	U58307-47080 PANEL SUB-ASSY, BODY	1.00	1058.90		1058.90
24	1	U58308-47030 COVER SUB-ASSY, RR	1.00	757.90		757.90
25	2	U67005-47460 PANEL SUB-ASSY, BACK	1.00	1692.80		1692.80
26	3	T67881-47030 WEATHERSTRIP, BACK	1.00	463.80		463.80
27	4	U68105-47170 GLASS SUB-ASSY, BACK	1.00	1675.30		1675.30
28	5	U56117-50140 DAM, WINDOW GLASS	1.00	40.10		40.10
29	6	U75310-47020 EMBLEM ASSY,	1.00	87.90		87.90
30	7	U75442-47080 PLATE, BACK DOOR	1.00	87.90		87.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 10/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU80J028363		2ZR0B89973	60	Sam San Joi	02/08/2024 8.00		12/08/2024 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
31	8	U75441-47130 PLATE, LUGGAGE COMPT			1.00	75.70		75.70
32	9	U81551-47262 LENS & BODY, RR			1.00	1069.50		1069.50
33	0	T81496-21010 GUIDE, RR			2.00	5.00		10.00
34	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00
35	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
36	3	U17430-37480 PIPE ASSY, EXHAUST			1.00	1153.00		1153.00
37	4	U17410-37572 PIPE ASSY, EXHAUST,			1.00	7767.80		7767.80
For & on behalf of		Customer's Signature		Charge Summary		Total		29,318.35
Borneo Motors (Singapore) Pte Ltd						GST 9.00%		2,638.65
		Please acknowledge receipt of vehicle		Parts 19,549.55		Less		0.00
				Labour 9,668.00		Amount Due		31,957.00
				Sublet 100.80				
				Lubrication/Fluid 0.00				
				Others 0.00				

Company Copy