

REF: CS/TP24080022/Avh3

ASSIGNMENT

From: _____ Date: _____
Estn: _____
OD / TP RES / OD RES / EVA / INV / MV
To in Vehicle No: _____
at _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: GBE309K Yr Regn: 2015 August
Type: M.Car / M.Cycle / Bus / Van / Tray / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Dyna CO: 2982
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 338426 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTFAT35X50K204.798
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In Order / Jammed / Leaked / Burnt or _____
Brake: In Order / Jammed / Leaked / Burnt or _____
Modif: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 195R15C
R: 155R12C

(Policy Condition)
Remarks: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front Rear
R/Bal. 06 mm R/Bal. 06 mm
L/Bal. 06 mm L/Bal. 06 mm
D.O.A. 26/7/2024 D.O.I. 30/07/24
Survey held at JL Perfect
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/10/24	TP 1st Rep. (Independent) COE Expiry: _____ Adrian confirmed LS \$6600 (Red 18,394.73, 73%) Estimate given during: Yes (✓) 1st Survey: No () MV: 231C PV: 1K Nett: 221C 548H

Date/Time, File Pass to? : Preli. Report : Final Report
Days Of Repair: 8
Resurvey No. of Trip: _____
Date/Time, File Return to? _____
Addl Fee: : Site Insp (\$) : Interview (\$) : Tech. Invoice
Survey Fee: _____
Transportation: _____
Photos: _____
Others: _____

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBE309K**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 26.07.2024
 TIME OF ACCIDENT : 16.50 HOURS

23	AIR CON COOLING COIL <i>checked</i>	1	\$ 2,439.00	\$ 2,439.00	✓
24	AIR CON PIPE	2	\$ 475.00	\$ 950.00	+
25	AIR CON CONDENSER	1	\$ 826.80	\$ 826.80	+
26	AIR CON FAN COWLING C/W MOTOR	1	\$ 498.90	\$ 498.90	+
27	AIR CON CONDENSER BRACKET	1	\$ 246.70	\$ 246.70	+

TOTAL PRICE \$ 21,366.30
 LESS 25% \$ 5,341.58
SUB TOTAL PRICE \$ 16,024.73

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>detached</i>	1	\$ 50.00	\$ 50.00	30
2	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	30
3	FRONT PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	60
4	FRONT DOOR SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	+
5	FRONT DOOR LTA STICKER (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
5	DASHBOARD CLIP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00	+
6	DASHBOARD CENTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	FRONT WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
8	FRONT WINDSCREEN GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
9	FRONT ERP BRACKET <i>new</i>	1	\$ 40.00	\$ 40.00	+
10	DOOR VISOR <i>new</i>	1	\$ 180.00	\$ 180.00	+

TOTAL \$ 1,010.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 2,000.00	800
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,800.00	800
3	TO SPRAY TUFF COAT	\$ 250.00	60
4	WIRING, BULB CHECKING	\$ 80.00	30
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	+

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBE309K**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 26.07.2024
 TIME OF ACCIDENT : 16.50 HOURS

6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	X
7	REFOCUS HEADLAMP BEAM	\$ 60.00	X
8	REMOVE AND REFIX DOOR WINDOR GLASS	\$ 80.00	X
9	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	X
8	REMOVE AND REFIX AIRCON BLOWER, COOLING COIL, AIR CON CONDENSER AND REFILL AIRCON GAS	\$ 250.00	X
9	REMOVE AND REINSTALL DASHBOARD	\$ 650.00	X
10	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓
11	REMOVE AND REFIX FRONT VIDEO RECORDER	\$ 80.00	X
12	RESET RADIO SYSTEM	\$ 200.00	X
13	LIFT UP CABIN	\$ 1,800.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 7,960.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,034.73
 TOTAL LABOUR COST : \$ 7,960.00
 TOTAL REPAIR COST : \$ 24,994.73

Adriani
 1/8 30/08/24

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

08 Days

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: