



TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBE309K**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 26.07.2024  
 TIME OF ACCIDENT : 16.50 HOURS

1350

|    |                                     |   |             |                        |
|----|-------------------------------------|---|-------------|------------------------|
| 23 | AIR CON COOLING COIL <i>checked</i> | 1 | \$ 2,439.00 | \$ <del>2,439.00</del> |
| 24 | AIR CON PIPE                        | 2 | \$ 475.00   | \$ 950.00 +            |
| 25 | AIR CON CONDENSER                   | 1 | \$ 826.80   | \$ 826.80 +            |
| 26 | AIR CON FAN COWLING C/W MOTOR       | 1 | \$ 498.90   | \$ 498.90 +            |
| 27 | AIR CON CONDENSER BRACKET           | 1 | \$ 246.70   | \$ 246.70 +            |

8309.20  
6231.90

TOTAL PRICE \$ 21,366.30  
 LESS 25% \$ 5,341.58  
 SUB TOTAL PRICE \$ 16,024.73

| S/N | DESCRIPTION                                    | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--|-----|-------------|--------------|
| 1   | FRONT NUMBER PLATE <i>Dented</i>               | 1   | \$ 50.00    | \$ 50.00 30  |
| 2   | FRONT GRILLE CLIP (SET) <i>new</i>             | 1   | \$ 40.00    | \$ 40.00 30  |
| 3   | FRONT PANEL SEALANT <i>new</i>                 | 1   | \$ 150.00   | \$ 150.00 60 |
| 4   | FRONT DOOR SEALANT LH <i>new</i>               | 1   | \$ 150.00   | \$ 150.00 +  |
| 5   | FRONT DOOR LTA STICKER (SET) <i>new</i>        | 1   | \$ 60.00    | \$ 60.00 30  |
| 5   | DASHBOARD CLIP (SET) <i>new</i>                | 1   | \$ 150.00   | \$ 150.00 +  |
| 6   | DASHBOARD CENTER GARNISH CLIP (SET) <i>new</i> | 1   | \$ 50.00    | \$ 50.00 +   |
| 7   | FRONT WINDSCREEN GLASS SEALANT <i>new</i>      | 1   | \$ 80.00    | \$ 80.00 40  |
| 8   | FRONT WINDSCREEN GLASS INNER SEAL              | 1   | \$ 60.00    | \$ 60.00 30  |
| 9   | FRONT ERP BRACKET <i>new</i>                   | 1   | \$ 40.00    | \$ 40.00 +   |
| 10  | DOOR VISOR <i>new</i>                          | 1   | \$ 180.00   | \$ 180.00 +  |

220

TOTAL \$ 1,010.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

| S/N | JOB DESCRIPTION                         | PRICE                  | ADJUSTED COST |
|-----|---|------------------------|---------------|
| 1   | TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK | \$ <del>2,000.00</del> | 800           |
| 2   | TO PUTTY, SPRAY PAINT, POLISH WAX       | \$ <del>1,800.00</del> | 800           |
| 3   | TO SPRAY TUFF COAT                      | \$ <del>250.00</del>   | 60            |
| 4   | WIRING, BULB CHECKING                   | \$ <del>80.00</del>    | 30            |
| 5   | CONDUCT WATER TER LEAKAGE TEST          | \$ 80.00               | X             |

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBE309K**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 26.07.2024  
 TIME OF ACCIDENT : 16.50 HOURS

|    |  |             |   |
|----|--|-------------|---|
| 6  | REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR                   | \$ 250.00   | X |
| 7  | REFOCUS HEADLAMP BEAM  | \$ 60.00    | X |
| 8  | REMOVE AND REFIX DOOR WINDOR GLASS   | \$ 80.00    | X |
| 9  | TRANFER FRONT DOOR MECHANISM   | \$ 80.00    | X |
| 8  | REMOVE AND REFIX AIRCON BLOWER, COOLING COIL, AIR CON CONDENSER AND REFILL AIRCON GAS          | \$ 250.00   | X |
| 9  | REMOVE AND REINSTALL DASHBOARD   | \$ 650.00   | X |
| 10 | REMOVE AND REFIX FRONT WINDSCREEN  | \$ 120.00   | ✓ |
| 11 | REMOVE AND REFIX FRONT VIDEO RECORDER  | \$ 80.00    | X |
| 12 | RESET RADIO SYSTEM   | \$ 200.00   | X |
| 13 | LIFT UP CABIN  | \$ 1,800.00 | X |
| 14 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00   | X |

1810

**TOTAL \$ 7,960.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 17,034.73  
 TOTAL LABOUR COST : \$ 7,960.00  
 TOTAL REPAIR COST : \$ 24,994.73

total: 8261.90  
 2/s: 66K ✓  
 Admin Lj  
 2/s 30/08/24

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

08/08/24