



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	JL PERFECT AUTOWORK PTE LTD	Ref:	CS/TP24080022/Avh3e2	
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875	Date:	28/10/2024	
	ON BEHALF OF GCE STRUCTURAL PTE LTD	Code:	TP564	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b> -	<b>Veh. Inspected</b>	GBE 309K	
	<b>Policy No.</b> -	<b>Coverage</b>	0	
	<b>Claim No.</b> -	<b>Excess</b>	\$0.00	
	<b>Assign From</b> -	<b>Assign Date</b>	30/07/2024	
<b>2. Vehicle Details</b>				
	<b>Make &amp; Model</b> TOYOTA DYNA	<b>C.C</b>	2982	
	<b>Engine No.</b> 1KD2546321	<b>Year of Reg.</b>	18/08/2015	
	<b>Chassis No.</b> JTFAT35Y50K204798	<b>Colour</b>	SILVER	
	<b>Odometer</b> 338426 KM	<b>Steering</b>	IN ORDER	
	<b>Brakes</b> IN ORDER	<b>General</b>	GOOD	
	<b>Modification(s)</b> RIMS: NIL			
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance (mm)</b>
	<b>R/H Front Tyre</b>	195 R15	YOKOHAMA	6
	<b>L/H Front Tyre</b>	195 R15	YOKOHAMA	6
	<b>R/H Rear Tyre</b>	155 R12C	YOKOHAMA	6
	<b>L/H Rear Tyre</b>	155 R12C	YOKOHAMA	6
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	<b>Accident Date</b> 26/07/2024	<b>Inspection Date</b>	30/07/2024	
	<b>Survey held at</b> JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				