



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080023/Aqh3
75 BRAS BASAH ROAD	Date:	07/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 2496J	Veh. Inspected	SNQ 295K
Policy No.	-	Coverage	0
Claim No.	MT/1288887-001	Excess	\$0.00
Assign From	MARCUS XIAO	Assign Date	01/08/2024

2. Vehicle Details

Make & Model	TOYOTA VELLFIRE	C.C	2493
Engine No.	2ARH618020	Year of Reg.	21/02/2017
Chassis No.	AGH300035688	Colour	BLACK
Odometer	136585 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55 R18	ALTENZO	6
L/H Front Tyre	235/55 R18	ALTENZO	6
R/H Rear Tyre	235/55 R18	ALTENZO	6
L/H Rear Tyre	235/55 R18	ALTENZO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/07/2024	Inspection Date	14/08/2024 (11:43)
Survey held at	1 KAKI BUKIT AVENUE 6 #01-77 AUTOBAY SINGAPORE 417883 - REPAIRER: JEC AUTO SERVICE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days