

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	: NTUC	DATE	: 14/8/2024
VEHICLE NO	: SNQ295K (2017)	TP INC	
VEHICLE MODEL	: TOYOTA VELLFIRE	Xiao Chen	
CHASSIS NO	: AGH300035688		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehnd</i>	1	\$ 885.90	\$ 885.90
2	REAR BUMPER SIDE HOLDER <i>cut d</i>	1	\$ 103.40	\$ 103.40
3	REAR BUMPER IMPACT BRACKET <i>Dehnd</i>	1	\$ 165.10	\$ 165.10
4	REAR BUMPER TOW COVER <i>Dehnd</i>	1	\$ 24.20	\$ 24.20
	REAR BUMPER REFLECTOR <i>cut d</i>	1	\$ 92.10	\$ 92.10
5	REAR BUMPER SENSOR <i>1 piece damaged</i>	2	\$ 417.80	\$ 835.60
6	REAR BUMPER SENSOR O RING <i>1 piece new</i>	2	\$ 24.10	\$ 48.20
7	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 330.90	\$ 330.90
8	REAR BUMPER UNDER COVER <i>new</i>	1	\$ 155.70	\$ 155.70
9	REAR END PANEL <i>3 piece</i>	1	\$ 781.10	\$ 781.10
10	REAR END PANEL INNER	1	\$ 964.60	\$ 964.60
11	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 195.90	\$ 195.90
12	REAR END PANEL BUZZER <i>3 pc</i>	1	\$ 148.60	\$ 148.60
13	REAR END PANEL ANTENNA SENSOR <i>new</i>	1	\$ 194.70	\$ 194.70
14	TAILLAMP <i>new</i>	1	\$ 689.20	\$ 689.20
15	TAILLAMP LOWER APRON <i>Dehnd</i>	1	\$ 341.40	\$ 341.40
16	TAILLAMP LOWER APRON RETAINER <i>new</i>	1	\$ 65.10	\$ 65.10
17	TAILGATE <i>Dehnd</i>	1	\$ 2,040.50	\$ 2,040.50
18	TAILGATE LOCK <i>new</i>	1	\$ 800.70	\$ 800.70
19	TAILGATE AUTO LOCK MOTOR <i>new</i>	1	\$ 2,812.70	\$ 2,812.70
20	TAILGATE AUTO LOCK SIDE SENSOR <i>new</i>	1	\$ 877.60	\$ 877.60
21	TAILGATE AUTO DAMPER <i>new</i>	2	\$ 351.80	\$ 703.60
22	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 324.70	\$ 324.70
23	TAILGATE OUTER CHROME MOULDING <i>new</i>	1	\$ 680.80	\$ 680.80
24	TAILGATE REFLECTOR <i>3 pc</i>	1	\$ 609.40	\$ 609.40
25	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 734.90	\$ 734.90
26	TAILGATE GLASS C/W MOULDING <i>new</i>	1	\$ 1,297.40	\$ 1,297.40
27	TOYOTA LOGO <i>new</i>	1	\$ 78.20	\$ 78.20
28	VELLFIRE MORDING <i>new</i>	1	\$ 75.60	\$ 75.60
29	REAR FENDER INNER TRIM BOARD <i>new</i>	1	\$ 2,024.20	\$ 2,024.20
30	REAR EXHAUST PIPE	1	\$ 987.50	\$ 987.50
31	REAR EXHAUST PIPE MOUNTING <i>3 pc</i>	1	\$ 39.80	\$ 39.80
32	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 35.40	\$ 35.40
33	AIR CON BLOWER	1	\$ 1,869.70	\$ 1,869.70

TOTAL PRICE: \$ 22,014.40
LESS 25% \$ 5,503.60
SUB TOTAL PRICE: \$ 16,510.80

4397.30
3297.97

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER UNDER COVER CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	TAILLAMP LOWER APRON CLIPS (SET) <i>new</i>	2	\$ 20.00	\$ 40.00
6	TAILGATE OUTER CHROME MOULDING CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
7	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
8	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
9	REAR FENDER INNER TRIM BOARD CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00
			TOTAL :	\$ 360.00

130

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	300	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	400	
3	WIRING CHECK	\$ 50.00	30	
4	TO REMOVE REAR BUMPER SENSOR	\$ 100.00	50	
5	TO REMOVE UPHOLSTERY	\$ 150.00	30	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	50	
8	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
10	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	X	
11	TO REMOVE AIR CON BLOWER & TO TOP UP AIR CON GAS	\$ 250.00	X	

TOTAL: \$ 3,630.00

1990

ESTIMATE REPORT

TOTAL PARTS COST: \$ 16,870.80

TOTAL LABOUR COST: \$ 3,630.00

TOTAL REPAIR COST: \$ 20,500.80

Total: 5417.97

L/S: 43K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

43K