

dnata

Company Name: SATS Airport Services
Contact Name: Mr. Tan Xiang Jian (Assistant Manager, Apron Safety System)
Address: 20 Alport Boulevard, SATS Inflight Catering 1,
Singapore 819659
Email Address: xiangjian_tan@sats.com.sg
Tel: 65 83332494

Equipment ID:
Vehicle Nos: RU5008Y(VC03-1)

S/No	Description	Qty	UOM	Rate	Amount
1	Supply labour, tools & material to carry out accident repair as following:				
	a. Supply rear bumper	1	Ea	398.25	398.250
	b. Supply LHR retainer	1	Ea	60.75	60.75
	c. Supply end door	1	Ea	1147.50	1147.50
	d. Supply LHR lamp assy	1	Ea	297.00	297.000
	e. Supply both door weatherstrips	1	Lot	405.00	405.00
	f. Replace rear end door, glass, repair end panel & end floor panel, rear LH fender, panel, bumper & weatherstrip	1	Lot	3240.00	3240.00
	g. Respray rear end door, end panel, LHR fender, panel & bumper.	1	Lot	1309.50	1309.50
	h. Replace & reseal number plate	1	Lot	337.50	337.50
	i. Towing charges (2 ways)	1	Lot	324.00	324.00
	LAST ITEM--				

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

Total (\$)	7519.50
GST 9% (\$)	676.76
Amount Payable (\$)	8196.26

- 1) Price quoted are valid for 30 days from date indicated on this quotation
- 2) Prices indicate are for one service of one vehicle only.
- 3) Price quoted exclude repair & spare parts replacement

10 days

Quoted By: Terence Tan

Company stamp, date and signature

dnata stamp, date & signature