

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24080030/KVP3M4**Date:** 15/08/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002962103		
Claimant Vehicle No :	SMX7780E	Insured Vehicle No :	FBV1679X		
Date of Loss:	17/07/2024	Nature of Claim:	TP	Claim No:	367318

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX7780E	Engine No:	2ZR2H28800
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU503092977
Reg. Date:	29/01/2021 (Man. Year: 2020)	Odometer:	240253 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Wanda 8 mm	Rear Left Side:	Wanda 8 mm
Front Right Side:	Wanda 8 mm	Rear Right Side:	Wanda 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,800.75	2,854.63	946.12	24.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	620.00	800.00	56.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,220.75	3,474.63	1,746.12	33.45
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	5,220.75	2,750.00	2,470.75	47.33
+ GST 9.00/9.00% (S\$)	469.87	247.50	222.37	47.33
Nett Amount (S\$)	5,690.62	2,997.50	2,693.12	47.33

INSPECTION

Date of Assignment:	02/08/2024	
Date Inspected:	02/08/2024 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat #05-67/68, Carros Centre Singapore 737869
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX7780E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent	879.00 FL	*653.31 FL
2	1		*FRT BUMPER SIDE RETAINER RH	Serviceable	45.00 FL	*- FL
3	1		*FRT BUMPER SIDE GARNISH RH	Cut	112.00 FL	*112.00 FL
4	1		*FRT BUMPER LOWER	Cut	512.00 FL	*301.90 FL
5	1		*FRT BUMPER TOWING COVER	Missing	112.00 FL	*29.30 FL
6	1		*HEADLAMP RH	Cut	2,591.00 FL	*2,591.00 FL
7	1		*FRONT FENDER RH	Repair	698.00 FL	*- FL
8	1		*FRONT FENDER EMBLEM RH	Necessary	52.00 FL	*52.00 FL
9	1		*SET FRT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	5,051.00 3,789.51
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,250.25 934.88
					Total Parts (\$\$)	3,800.75 2,854.63

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING }	New	100.00	20.00
2	REALIGN HEADLAMP }	New	120.00	0.00
3	PANEL BEAT	New	600.00	200.00
4	SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$\$)			1,420.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >