



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS/SMO24080033/Anp3m4 (N)
50 RAFFLES PLACE #03-03			Date:	20/02/2025
SINGAPORE LAND TOWERSINGAPORE 048623			Code:	SMO
ATTN: AGNES				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFU 391P	Veh. Inspected	PC 8901S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2402513/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/08/2024	
2. Vehicle Particulars & Condition				
Make & Model	SC NEUSTAR CA36	c.c	10837	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	PF9SCAD36KS003025	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80R22.5	POWERTRAC	6 mm	
L/H Front Tyre	295/80R22.5	POWERTRAC	6 mm	
R/H Rear Tyre	295/80R22.5	POWERTRAC	6 mm	
L/H Rear Tyre	295/80R22.5	POWERTRAC	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2024	Inspection Date	17/12/2024	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	