



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 05/09/2024	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	17/03/2017	SLL9839H	0	31996	67/TP/SLL9839H
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3X02007944		2NRX133347	60	Sam San Joi	12/08/2024 8.00		14/08/2024 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SJV1775G ACC DATE:01/08/2024 DRIVE IN:01/08/2024 DATE-IN:12/08/2024 DATE SURVEY:12/08/2024 NO OF REPAIR DAYS:5 DAYS BY:RASUL(LKK)				50.00	
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM *				158.40	
3	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT BP64				158.40	
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME BP64				158.40	
5	B	BP-LAB2 REPLACE LH FRT ACCIDENT DAMAGED PARTS *				950.40	
6	B	BP-RES2 STRAIGHTEN & ALIGN LH ACCIDENT AFFECTED AREAS *				1049.60	
7	B	BP-MECH2 RESPRAY JOB ON LH FRT ACCIDENT AFFECTED AREAS				126.72	
8	1	BP-MECH2 REPLACE RIM AND WHEEL BALANCING <i>Supplier</i> BP64	1.00	1067.30	30.00	747.11	
9	2	K53812-K0020 PANEL, FR FENDER, LH	10.00	3.80	30.00	26.60	
10	3	U90467-07214 CLIP	1.00	2687.30	30.00	1881.11	
For & on behalf of		Customer's Signature	Charge Summary			Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle				5,306.74	
						GST 9.00%	
						477.61	
						Less	
						0.00	
			Parts	2,654.82			
			Labour	2,651.92			
			Sublet	0.00			
			Lubrication/Fluid	0.00			
			Others	0.00			
			Amount Due			5,784.35	

Company Copy