



|                |             |
|----------------|-------------|
| Vehicle number | SME2325U    |
| Make / Model   | HONDA GRACE |
| Chassis number | GM41201713  |
| Accident date  | 30/7/24     |
| Reference      | 2407-34     |

| Qty                                           | Particulars                               | Unit Price - SGD \$ |
|-----------------------------------------------|-------------------------------------------|---------------------|
| <b>PARTS REPLACEMENT - LIST ITEMS</b>         |                                           |                     |
| 1                                             | REAR BUMPER / OR                          | 510.67 /            |
| 1                                             | REAR BUMPER LOWER GRILLE / CRU            | 94.85 /             |
| 2                                             | REAR BUMPER RETAINER / BR                 | 86.80 /             |
| 2                                             | REAR BUMPER REFLECTOR (LH) ? x nn         | 128.66              |
| 2                                             | REAR BUMPER REFLECTOR COVER (LH) / CVT    | 160.32 80.16 /      |
| 1                                             | BOOTLID / OD                              | 952.20 872 /        |
| 1                                             | BOOTLID LOCK / BT                         | 281.20 /            |
| 1                                             | BOOTLID LOCK STRIKER X nn                 | 23.90               |
| 1                                             | BOOTLID WEATHERSTRIP / CRU                | 139.20 /            |
| 2                                             | BOOTLID LAMP / CVT                        | 724.28 /            |
| 1                                             | BOOTLID OUTER CHROME GARNISH / BR         | 198.62 /            |
| 1                                             | BOOTLID EMBLEM - LOGO / BR                | 48.70 /             |
| 1                                             | BOOTLID INNER TRIM X nn                   | 225.49              |
| 2                                             | BOOTLID HINGE X nn                        | 194.58              |
| 2                                             | TAILLAMP / BR / CVT                       | 1380.72 /           |
| 1                                             | END PANEL / OD                            | 564.26 495 /        |
| 1                                             | END PANEL TOP GARNISH / OR                | 128.80 /            |
| 1                                             | SPARE TYRE TOP BOARD X nn                 | 377.60              |
| 1                                             | SPARE TYRE COMPARTMENT / OD               | 916.60 /            |
| 2                                             | REAR FENDER X R                           | 2829.20             |
| 2                                             | REAR ENDER INNER TRIM (LH) / OLF          | 456.56 228.28 /     |
| 1                                             | EXHAUST SILENCER X nn                     | 523.93              |
| 2                                             | EXHAUST SILENCER MOUNTING X nn            | 29.30               |
| 1                                             | EXHAUST SILENCER HEATSHEILD X nn          | 85.60               |
|                                               |                                           | 11062.04            |
|                                               | Less 20%                                  | 2212.41             |
|                                               | Subtotal                                  | 8849.63             |
| <b>PARTS REPLACEMENT - SPECIAL NETT ITEMS</b> |                                           |                     |
| 1 SET                                         | REAR BUMPER CLIP / MC                     | 30.00 /             |
| 1 SET                                         | REVERSE SENSPR / OR                       | 200.00 /            |
| 1 SET                                         | BOOTLID INNER TRIM CLIP X nn              | 30.00               |
| 1 SET                                         | REAR FENDER INNER TRIM CLIP / MC          | 30.00               |
| 1                                             | REAR NUMBER PLATE / CVT                   | 20 / 30.00          |
|                                               |                                           | 50 / 60.00          |
|                                               | Subtotal                                  | 350.00              |
| <b>LABOUR AND MISCELLANEOUS CHARGES</b>       |                                           |                     |
| 1                                             | CHECK WIRING AND LIGHTING SYSTEM          | 80.00 30            |
| 2                                             | REMOVE AND REFIT REAR TRIMS AND GARNISHES | 150.00 80           |
| 3                                             | REMOVE AND REPLACE REVERSE SENSOR         | 150.00 30           |
| 4                                             | REMOVE AND REPLACE EXHAUST SILENCER       | 200.00 Y            |
| 5                                             | PANEL BEATING ON AFFECTED AREAS           | 1600.00 1400        |
| 6                                             | SPRAY PAINTING ON AFFECTED AREAS          | 1600.00 1200        |
| 7                                             | APPLY ANTI-RUST ON AFFECTED AREAS         | 80.00 30            |
|                                               | Subtotal                                  | 3860.00             |
|                                               | Granttotal                                | 13059.63            |

6185.88  
-20%  
4948.70

300

2770

8018.70

L/S - 6414.96  
= 6400

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Store (LKK)  
2/8/24, 12.00p  
m IL  
L/S  
AL  
10 days