8/15/24, 4:04 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24080037/EVP3M4

Date: 15/08/2024

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1002385084 **Claimant Vehicle** 

SHD3669K Insured Vehicle No: EE3238B No:

Date of Loss: 01/08/2024 Nature of Claim: ΤP Claim No: 369034

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SHD3669K Reg No:

TOYOTA PRIUS, 1.8 HYBRID CVT (A) Make & Model: Engine No: 2ZRS043966

Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403557247

Colour: Blue Odometer: 684559 km

**Engine Capacity:** 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: West Lake 4 mm West Lake 4 mm Front Right Side: West Lake 4 mm Rear Right Side: West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,037.42	1,120.40	917.02	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	720.00	120.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,877.42	1,840.40	1,037.02	36.04
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	2,877.42	1,450.00	1,427.42	49.61
+ GST 9.00/9.00% (S\$)	258.97	130.50	128.47	49.61
Nett Amount (S\$)	3,136.39	1,580.50	1,555.89	49.61

INSPECTION

Date of Assignment: 05/08/2024

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 02/08/2024 Inspected At:

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2024)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3669K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty P	art No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	503.04 FL	*503.04 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*TAIL LAMP RH LOWER	Not Necessary	570.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	94.80 FL	*- FL
5	1		*REAR BUMPER LOWER COVER	Cut	654.96 FL	*654.96 FL
6	1		*REAR BUMPER EXTENSION LH	Broken	148.40 FL	*148.40 FL
7	1		*TAIL LAMP UPPER LH	Not Necessary	557.90 FL	*- FL
8	1		*REAR BUMPER TOWING COVER	Missing	98.80 FL	*98.80 FL
9	1	-1 0 0 N	*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
r=rra	inchise pai	ігт. S=SpciN	ett. L=ListItemDisc.	Sub Total (S\$)	2,699.90	1,477.20
			- List Item Discount	on L Items 25.00/25.00% (S\$)	662.48	356.80
				Total Parts (S\$)	2,037.42	1,120.40
			Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
4	CHECK ALL LIGHTING	New	80.00	30.00
		Gross Labour Cost (S\$)	840.00	720.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >