

ASS. REC. BY:

REF:

AG21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 5005R Yr Regn: 10, 21

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M/A180 C.G. 1332

Colour

M. Black A/C: Insured / Std / NI / NA

Sp. Reading

100855 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WIK1770842J324756

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / Sedan / STA / Rlm or

Tyre Size:

F: 225/45R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

L/Bal.

mm

D.O.A.

24/7/24

Rear

R/Bal.

mm

L/Bal.

mm

D.O.I.

5/8/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

FAX :

ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT202408-000001(00)

DATE : 02/08/2024

POLICY NO : SP2003907937

VEH REG NO : SNC5605R

MAKE/MODEL : MERCEDES BENZ A180
COMPACT SALOON
PROGRESSIVE

CHASSIS NO : W1K1770842J324756

ENGINE NO : 28291480677039

REG. DATE : 2021

YOUR REF NO : SNB648E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F

ACCIDENT DATE : 24/07/2024

TP VEH REG NO : SNB648E

Not Authorized
Return B4 pain
12 days

Estimate Repair Cost to Vehicle No : SNC5605R

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Roof top moulding - RH / LH	2	220.00	440.00 ✓
2 Bonnet	1	1,875.00	1,875.00 ✓
3 Bonnet hinges - RH / LH	2	98.00	196.00 ?
4 Bonnet actuator - RH / LH	2	270.00	540.00 ?
5 Bonnet seal	1	34.00	34.00 ✓
6 Bonnet catch	1	62.00	62.00 ?
7 Bonnet lock	1	215.00	215.00 ?
8 Bonnet lock switch	1	158.00	158.00 ?
9 Bonnet cable	1	82.00	82.00 X
10 Air intake hose	1	472.00	472.00 ✓
11 Support panel	1	865.00	865.00 ✓
12 Support panel mounting pin - RH / LH	2	36.00	72.00 ?
13 Support panel air duct	1	60.00	60.00 ?
14 Front grille	1	1,009.00	1,009.00 ✓
15 Front grille beam	1	322.00	322.00 ✓
16 Front grille beam moulding - RH / LH	2	78.00	156.00 ✓
17 Front grille centre logo	1	190.00	190.00 ✓
18 Front grille logo base	1	200.00	200.00 ✓
19 Headlamp assy - RH / LH	2	3,686.00	7,372.00 ✓
20 Headlamp control unit - LH	1	598.00	598.00 ?
21 Front fender - RH / LH	2	780.00	1,560.00 ✓
22 Front fender inner shield - RH / LH	2	235.00	470.00 X
23 Front fender rail - RH / LH	2	24.00	48.00 ?
24 Front fender bracket - RH	1	52.00	52.00 ?
25 Front bumper	1	1,435.00	1,435.00 ✓
26 Front bumper emblem	1	102.00	102.00 ✓
27 Front bumper top garnish - centre	1	220.00	220.00 ✓
28 Front bumper top garnish - RH / LH	2	130.00	260.00 ?
29 Front bumper reinforcement	1	518.00	518.00 ?
30 Front bumper reinforcement bracket - LH	1	180.00	180.00 ?
31 Front bumper lower cross frame	1	538.00	538.00 ?
32 Front bumper side retainer - RH / LH	2	24.00	48.00 ✓



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SNB648E
CLAIM TYPE : THIRD PARTY
TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F
ACCIDENT DATE : 24/07/2024
TP VEH REG NO : SNB648E

ESTIMATE

NO : QUOT202408-000001(00)
DATE : 02/08/2024
POLICY NO : SP2003907937
VEH REG NO : SNC5605R
MAKE/MODEL : MERCEDES BENZ A180
COMPACT SALOON
PROGRESSIVE
CHASSIS NO : W1K1770842J324756
ENGINE NO : 28291480677039
REG. DATE : 2021

Estimate Repair Cost to Vehicle No : SNC5605R

Description	Quantity	Unit Price	Amount
		S\$	S\$
33 Front bumper sponge	1	210.00	210.00 ✓
34 Front bumper pressure switch sensor	1	252.00	252.00 ?
35 Front bumper centre grille	1	184.00	184.00 ✓
36 Front bumper fog lamp cover - RH / LH	2	54.00	108.00 ✓
37 Front bumper sensor	4	216.00	864.00 ?
38 Front bumper sensor seals	6	12.00	72.00 ?
39 Front bumper radar sensor	1	1,436.00	1,436.00 ?
40 Front bumper radar sensor bracket	1	58.00	58.00 ?
41 Front bumper number plate garnish	1	136.00	136.00 ✓
42 Front bumper under cover	1	368.00	368.00 ?
43 Front bumper clips	15	9.00	135.00 ✓
44 Front bumper top bracket	1	76.00	76.00 ?
45 Front bumper top bracket air duct	1	155.00	155.00 ?
46 Front bumper lower bracket	1	76.00	76.00 ?
47 Front bumper lower bracket air duct	1	162.00	162.00 ?
48 Air-con condenser	1	1,335.00	1,335.00 ?
49 Air-con condenser support bracket - RH / LH	2	322.00	644.00 ?
50 Radiator assy	1	1,564.00	1,564.00 ?
51 Radiator auto fan assy	1	1,025.00	1,025.00 ?
52 Radiator top covering	1	76.00	76.00 ✓
53 Tailgate	1	2,658.00	2,658.00 ✓
54 Tailgate weatherstrip	1	340.00	340.00 X
55 Tailgate hinges - RH / LH	2	177.00	354.00 X
56 Tailgate centre garnish	1	325.00	325.00 ✓
57 Tailgate centre logo	1	67.00	67.00 ✓
58 Tailgate centre logo clip	3	10.00	30.00 ✓
59 Tailgate "A180" emblem	1	165.00	165.00 ✓
60 Tailgate reflector - RH / LH	2	488.00	976.00 ✓
61 Rear end panel	1	1,340.00	1,340.00 ?
62 Taillamp assy - RH / LH	2	675.00	1,350.00 ✓
63 Taillamp lower bracket - RH / LH	2	90.00	180.00 ?
64 Rear bumper	1	1,554.00	1,554.00 ✓
65 Rear bumper reinforcement	1	570.00	570.00 ?



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SNB648E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F REG. DATE : 2021

ACCIDENT DATE : 24/07/2024

TP VEH REG NO : SNB648E

ESTIMATE

NO : QUOT202408-000001(00)

DATE : 02/08/2024

POLICY NO : SP2003907937

VEH REG NO : SNC5605R

MAKE/MODEL : MERCEDES BENZ A180
COMPACT SALOON
PROGRESSIVE

CHASSIS NO : W1K1770842J324756

ENGINE NO : 28291480677039

Estimate Repair Cost to Vehicle No : SNC5605R

Description	Quantity	Unit Price	Amount
		S\$	S\$
66 Rear bumper side retainer - RH / LH	2	175.00	350.00 ✓
67 Rear bumper inner frame	1	190.00	190.00 ✓
68 Rear bumper lower garnish	1	358.00	358.00 ✓
69 Rear bumper lower chrome - centre	1	236.00	236.00 ✓
70 Rear bumper lower chrome - RH / LH	2	231.00	462.00 X
71 Rear bumper reflector - RH / LH	2	55.00	110.00 X
72 Rear bumper tow cover	1	28.00	28.00 ✓
73 Rear bumper sensor	2	216.00	864.00 ✓
74 Rear bumper sensor seals	6	12.00	72.00 ✓
75 Rear bumper clips	15	9.00	135.00 ✓
76 Rear exhaust end chrome	1	69.00	69.00 X
			42,068.00
		Less 10%	4,260.80
			37,807.20
SPECIAL NET			
77 Front number plate	1	40.00	40.00 ✓
78 Rear windscreen sealant	1	60.00	60.00 ✓
			100.00
LABOUR			
79 To remove & refit air-con condenser, radiator and refill air-con gas	1	150.00	150.00 100d
80 To remove & refit front and rear bumper sensor	1	200.00	200.00 120d
81 To check & rectify wiring system	1	160.00	160.00 40d
82 To remove & refit rear windscreen glass	1	150.00	150.00 120d
83 To panel beat & straighten front fender inner panel, front & rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit & adjust the same	1	2,500.00	2,500.00 120d
84 To putty & spray paint on affected areas	1	2,500.00	2,500.00 1400d
85 To apply rust-proofing on replace and repaired panels	1	250.00	250.00 ?
86 To reset & reprogram headlamp fault code	1	350.00	350.00 200d
			6,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJ0G2470000Q / JP Knights Pte Ltd
ENTRY DATE & TIME: 24/07/2024 14:31 (SGT)
SUBMITTED BY: Flash Reporting
VERSION: 1 (24/07/2024 14:31 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	24/07/2024 14:31 (SGT)
Reported by	Actual Driver
Date of Accident	24/07/2024 09:49 (SGT)
Exact Location of Accident	274A Toh Guan Rd, Singapore 600276
Additional Location Information	MULTI-STORY CARPARK DECK 1B
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNC5605R
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD
Company Reg No	1XXXXX778Z
Email Address	too_tong.tan@mercedes-benz.com
Mobile Phone No	(Phone) +65-96268394
Alternative Phone No	(Office) +65-82821711

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	A180 COMPACT SALOON PROGRESSIVE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1332

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003907937

DRIVER

Name of Driver	SIM HSIEN YON, IAN
NRIC No	SXXXX435D
Date Of Birth	08/10/1990

ON SNC CAR DEC

1 Please correctly report the

- ## 8. Consent under the Personal Data Protection Act (PDPA)

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

An aerial photograph of a road intersection. A vertical road runs through the center, and a horizontal road crosses it. Three vehicles are visible on the vertical road, moving downwards: a car labeled 'B' at the top, another car labeled 'B' in the middle, and a car labeled 'A' at the bottom. White arrows indicate the direction of traffic flow: two arrows point down on the vertical road, and one arrow points left on the horizontal road. White rectangular outlines represent buildings or structures along the roads. The text 'LOT 16' is visible at the bottom center of the image.

Page 4 of 19