



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :

ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT202408-000001(00)

DATE : 02/08/2024

POLICY NO : SP2003907937

VEH REG NO : SNC5605R

MAKE/MODEL : MERCEDES BENZ A180
COMPACT SALOON
PROGRESSIVE

CHASSIS NO : W1K1770842J324756

ENGINE NO : 28291480677039

REG. DATE : 2021

YOUR REF NO : SNB648E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F

ACCIDENT DATE : 24/07/2024

TP VEH REG NO : SNB648E

Estimate Repair Cost to Vehicle No : SNC5605R

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY			
NET PRICE			
1 Bonnet stopper - RH	1	42.00	42.00
2 Air-cleaner assy	1	455.00	455.00
3 Radiator holder - RH / LH	2	20.00	40.00
4 Water inter-cooler assy	1	1,765.00	1,765.00
5 Oil Filter pipe cover	1	12.00	12.00
6 Tailgate lock	1	360.00	360.00
7 Tailgate speaker board	1	1,272.00	1,272.00
8 Tailgate trimboard	1	175.00	175.00
9 Tailgate top trim	1	188.00	188.00
10 Rear exhaust heating shield	1	217.00	217.00
			4,526.00
		Less 10%	452.60
			4,073.40
LABOUR			
11 To remove & refit rear interior garnishes and trimboard to facilitates the repairs	1	280.00	280.00
			280.00
TOTAL			S\$ 4,353.40
ADD GST @ 9%			391.81
GRAND TOTAL			S\$ 4,745.21

SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED FORTY-FIVE AND CENTS TWENTY-ONE ONLY *4,193.40*

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE