



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080040/Kqh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	27/08/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 5967Y	Veh. Inspected	SMN 1587P
Policy No.	-	Coverage	0
Claim No.	AVS24/2378	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	02/08/2024

2. Vehicle Details

Make & Model	MAZDA CX-5 (A)	C.C	1998
Engine No.	PE31389671	Year of Reg.	26/07/2019
Chassis No.	JM6KF2W7AK0332538	Colour	METALLIC RED
Odometer	83275 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45ZR20	PIRELLI	9
L/H Front Tyre	245/45ZR20	PIRELLI	9
R/H Rear Tyre	245/45ZR20	FALKEN	7
L/H Rear Tyre	245/45ZR20	FALKEN	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/07/2024	Inspection Date	13/08/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days