

(08/11/13) wef

REF: n

ASS. REC. BY: Marcus

CS/11124060087/Unp3e2
111-24060087**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle-No: 5B E 23236at Workshop m/s my note

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 46k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: LIA 19903 Vehicle: IN / OUTVeh No: 5B E 23236Yr Regn: 05/04/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sientac.c. 1496Colour: whiteA/C: Insured / Std / NI / NASp. Reading: 115707T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NSP 170 702832xGen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or Michelin

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/06/24D.O.I. 13/6/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 14k24/6/24 but still \$1182.90
1/5 \$4700 infant David

(Red. \$ 4794.58, 50%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

1)

Date/Time, File Return to?

☐

Final Report

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$ _____)

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3148/06/24

Your Ref: [Faint text]

Date: 13rd June 2024

The Claim's Manager

Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.

6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Tan Teck Sin

Date Of Accident : 12/06/24 (12:40hrs)

Policy Number : D19MPC0001416_05

Estimate cost of repair to TOYOTA SIENTA 1.5 (A) S/Wgn - SBE 2323 E

1 pc front bumper	70.00	\$	496.70	—
6 pcs front bumper top clips	nm	@ \$	4.80	28.80
1 pc front bumper centre grille base	ee			944.10
10 pcs front bumper lower clips	nm	@ \$	4.80	48.80
1 pc front bumper n/s fog lamp assy	cm			355.60
1 pc front bumper n/s fog lamp garnish	70.00			143.80
1 pc front bumper n/s side retainer	cm			52.10
1 pc front support panel top garnish	11			139.30
6 pcs front top garnish clips	m.s	@ \$	3.90	23.40
1 pc n/s head lamp assy	320			1,090.50
1 pc front n/s fender	70.00 / 300			627.60
1 pc front n/s fender inner shield	70.00			186.70
6 pcs front n/s fender inner shield clips	nm	@ \$	3.90	23.40
1 pc front n/s door	2			1,280.40
1 pc front n/s door mirror with cover comp	cm			1,450.90
2 pcs front n/s door top & low hinge	11	@ \$	120.00	240.00
1 pc front n/s head lamp panel	300			85.20
1 pc front support panel	2			1,228.80
			\$	8,394.00
Less 25%			\$	2,098.50
			\$	6,295.50
To transfer front n/s door inner trim board, glass, hinge, weatherstrip, lock, moulding & necessary parts.			11	150.00
To check & adjust front wheel alignment & balancing.			11	150.00
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, n/s head lamp panel & necessary parts, to weld, renew & align above parts.				1,250.00
To putty & respray painting on all affected accident parts.				1,500.00
Towing charge.			11	60.00
To wiring check up & adjust headlight alignment.				50.00
			\$	9,455.50

Dollars : Nine Thousand Four Hundred Fifty Five And Cents Fifty Only.

HUP MOTOR TRADING & SERVICE

4/s \$4700

Not Authorized

LKH

new

Express \$800

Tel. 961. 11. 11

4/s \$4700

5-2-75

8446.10

6334.58

700

1000

30

9494.58

5557.6

252

4168.20

1730