

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3148/06/24

Your Ref:

Date: 13rd June 2024

The Claim's Manager
Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00, S(048580)

Name Of Insured : Mr Tan Teck Sin

Date Of Accident : 12/06/24 (12:40hrs)

Policy Number : D19MPC0001416-05

Estimate cost of repair to TOYOTA SIENIA 1.5 (A) S/Wgn - SBE 2323 E

1 pc front bumper	700	\$	496.70	---
6 pcs front bumper top clips	mm	@ \$	4.80	28.80
1 pc front bumper centre grille base	re			944.10
10 pcs front bumper lower clips	mm	@ \$	4.80	48.80
1 pc front bumper n/s fog lamp assy	cm			355.60
1 pc front bumper n/s fog lamp garnish	700			143.80
1 pc front bumper n/s side retainer	cm			52.10
1 pc front support panel top garnish	11			139.30
6 pcs front top garnish clips	m.s	@ \$	3.90	23.40
1 pc n/s head lamp assy	320			1,090.50
1 pc front n/s fender	20/304			627.60
1 pc front n/s fender inner shield	700			186.70
6 pcs front n/s fender inner shield clips	mm	@ \$	3.90	23.40
1 pc front n/s door	R			1,280.40
1 pc front n/s door mirror with cover comp	cm			1,450.90
2 pcs front n/s door top & low hinge	11	@ \$	120.00	240.00
1 pc front n/s head lamp panel	321			85.20
1 pc front support panel	R			1,228.80
		\$	8,394.00	8446.10
		Less 25%	\$	2,098.50
		\$	6,295.50	6334.58
To transfer front n/s door inner trim board, glass, hinge, weatherstrip, lock, moulding & necessary parts.	11		150.00	X
To check & adjust front wheel alignment & balancing.	11		150.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, n/s head lamp panel & necessary parts, to weld, renew & align above parts.			1,250.00	700
To putty & respray painting on all affected accident parts.			1,500.00	1000
Towing charge.	11		60.00	X
To wiring check up & adjust headlight alignment.			50.00	30
		\$	9,455.50	9494.58
		=====		

Dollars : Nine Thousand Four Hundred Fifty Five And Cents Fifty Only.

HUP MOTOR TRADING & SERVICE



45 4700

Not Authorized
LKH
mom
Express 8.000
5458

Take ph. At the 14.11

4/s \$ 4700

5-275

5557.6
252
4168.20
1730