



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

12 August 2024

REG NO.: SNN 4226 A
MAKE/MODEL: HONDA CIVIC

Not Authorised
6/8/24
1/3 \$2500
3 days
Take photo After repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front headlamp -RH	\$ 1,700.60 X
1	Front headlamp top moulding	\$ 227.50 X
1	Front headlamp lower bracket	\$ 97.60 X
1	Front grille base	\$ 188.50 X
1	Front grille logo	\$ 79.50 X
1	Front bumper bracket	\$ 68.50 X
2	Front bumper side retainers	\$ 85.20 X
1	Front bumper top beam	\$ 200.30 X
1	Front fender -RH	\$ 386.90 X
1	Front fender inner shield	\$ 149.60 X
1	Front fender signal lamp	\$ 85.50 X
		\$ 3,269.70
Less 20%		\$ 653.94
		\$ 2,615.76

SPECIAL NETT ITEMS

1	Front bumper assy	\$ 1,800.00	1300 S/N
1	Front bumper lower spoiler	\$ 850.00	800 S/N
1	Front bumper clip (1 set)	\$ 80.00	40 S/N
1	Front fender inner shield clip (1 set)	\$ 50.00	
		\$ 2,780.00	

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00	20
2	To apply undercoating.	\$ 100.00	X
3	Panel beating.	\$ 1,400.00	300
4	To re-spray painting on the affected areas.	\$ 1,300.00	600
		\$ 2,880.00	

LKK Auto Consultants hence notify **GRAND TOTAL :**

\$ 8,275.76

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date: