

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SNN 4226A
at Workshop m/s 200M
of _____
Insured: SJA 11254
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8626.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 11A @ 27833
Vehicle: IN / OUT

Veh No: SNN 4226A Yr Regn: 23/03/18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (A)
Make: Honda civic 1.6 c.c 1597
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 123243 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR HFC 5650J T 000084
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 235/40 R18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or greenlander
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 02/08/24 D.O.I. 6/8/24
Survey held at _____
Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
015 Ref.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/8/24	1/5 \$ 2500 : 14800 : 14800

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

12 August 2024

REG NO.: SNN 4226 A
MAKE/MODEL: HONDA CIVIC

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Front headlamp -RH 11	\$ 1,700.60 X
1	Front headlamp top moulding 11	\$ 227.50 X
1	Front headlamp lower bracket 11	\$ 97.60 X
1	Front grille base 11	\$ 188.50 X
1	Front grille logo 11	\$ 79.50 X
1	Front bumper bracket 11	\$ 68.50 X
2	Front bumper side retainers 11	\$ 85.20 X
1	Front bumper top beam 11	\$ 200.30 X
1	Front fender -RH R	\$ 386.90 X
1	Front fender inner shield 11	\$ 149.60 X
1	Front fender signal lamp 11 11	\$ 85.50 X
		\$ 3,269.70
Less 20%		\$ 653.94
		\$ 2,615.76

SPECIAL NETT ITEMS		
1	Front bumper assy cur/Torn	\$ 1,800.00 1300 S/N
1	Front bumper lower spoiler cur	\$ 850.00 800 S/N
1	Front bumper clip (1 set) 11	\$ 80.00 40 S/N
1	Front fender inner shield clip (1 set) 11	\$ 50.00
		\$ 2,780.00

LABOUR CHARGES		
1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To apply undercoating.	\$ 100.00 X
3	Panel beating.	\$ 1,400.00 300
4	To re-spray painting on the affected areas.	\$ 1,300.00 600
		\$ 2,880.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

GRAND TOTAL :
\$ 8,275.76