

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24080047/TMA3Q2**Date:** 18/11/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210066520
<b>Claimant Vehicle No :</b>	SMB1409J	<b>Insured Vehicle No :</b>	GBL3956K
Date of Loss:	28/07/2024	Nature of Claim:	TP
		Claim No:	8587381216SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMB1409J</b>	Engine No:	50334521593446
Make & Model:	MAN NL320F (A22), 10.5 D (A)	Chassis No:	WMAA22ZZXD7001913
Reg. Date:	06/01/2014 (Man. Year: 2013)	Odometer:	757088 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,724.90	3,201.75	1,523.15	32.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,938.00	1,503.00	435.00	22.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,662.90</b>	<b>4,704.75</b>	<b>1,958.15</b>	<b>29.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,050.00</b>		
<b>(S\$)</b>	6,662.90	4,050.00	2,612.90	39.22
<b>+ GST 9.00/9.00% (S\$)</b>	599.66	364.50	235.16	39.22
<b>Nett Amount (S\$)</b>	<b>7,262.56</b>	<b>4,414.50</b>	<b>2,848.06</b>	<b>39.22</b>
<b>+ Loss of Use (2.0 x S\$250.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>4,916.68</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,910.00</b>		

**INSPECTION**

Date of Assignment:	05/08/2024	<b>STRIDES PREMIER AUTOMOTIVE SERVICES PTE LTD - WOODLANDS (HQ) 60 WOODLANDS INDUSTRIAL PARK E4 Singapore 757705</b>
Date Inspected:	05/08/2024 Inspected At:	
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*LAMP STOP LED (MAN BUS)	Cracked	2,283.40 F	*2,283.40 FL
2	1		*LAMP INDICATOR LED (MAN BUS)	Cracked	1,274.10 F	*1,274.10 FL
3	1		*COVER REAR TAIL LAMP RH FOR MAN A22 BUS	Repair	974.70 F	*- FL
4	1		*PANEL SIDE R10 FOR MAN A22 BUS	Repair	192.70 F	*- FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (\$\$)	4,724.90	3,557.50
				- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	355.75
				Total Parts (\$\$)	4,724.90	3,201.75

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	878.00	708.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,938.00</b>	<b>1,503.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >