ASS. REC. BY: TOWARD	•	-	2 500 4
ACC DEC DV. TAWAWY	- <del> </del>	—	KEF
	ACC DEC DV.	1 rul IVIV	5.4 <del>22</del> 3 (5)
ACCOUNTED TO THE PARTY OF THE P	aco, rec. or.	1 4 7	

V	+	6	
	2.0		l

<u>ASS</u>	IGNMENT
From: Date:	Veh No: SMB14095 Yr Regn: 2014, 01
On / RO I and Date :	Турв: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD/P) WS/TP RES/OD RES/EVA/INV/MV	Truck / Traller or
to mahact Aeulcie MO:	Make: MAN A22 c.c 10518
at Workshop m/s	Colour Malh A/G: Insured/Std/NI/NA
Of	Sp.Reading 757088 T/Radio: Insured / Std / NI / NA
Insurext:	Eng/No:
Policy No.	C/No: NMAA 22 Z Z X D 7-01913
Claims No.	Gen. Cond: 600d / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh;	Modl: ND/S/Rim / STD A/Rim or
	Tyre Size: F: 275 90822.5
(Policy Condition)	R:(D)
Remark: The veh had commenced its  repair at the time of inspection.  N/S  O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or F / JULY
Bal. or Market Value:	
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 8
GIA / PR Seen: Consistent?: Yes or No	1/8al, 8 mm 1/8al 8-/6
Est Repairs: days Res.: Yes or No	D.O.A. D.O.I. 5/2/24
Lum Sum: % 3 Val.: Yes or No	Survey held at SMRT WL
CA I REV I REP. I 24 HRS \ \WP'	Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop- or
Date: Person Contacted: Vehicle: IN / OUT	Rear 0/5
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
·	
	· · · · · · · · · · · · · · · · · · ·
Date/Time, File Pass to? : Prell. Report	ays Of Repair:
i) : Final Report	Survey No. of Trip:
Dale/Time, File Return to?	Transportation:
Add Fee;	
	: Interview (\$ ) Photos
Popular Comment of the Comment of th	: Tech. Invs (\$ ) Others
Lump Sun / Le.k. (%)	: Meel:eluci (iz
	TOTAL



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 05/08/2024 User ID : choonhwee03

Section A - Accident Details			
Registration Number	SMB1409J		
Case Reference Number	BUS/07/24/5057		
Registration Date	1/6/2014		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	A22		
Name of Driver	Sun Shunxin		
Type of Accident	Head to Rear		
Accident Date and Time	7/28/2024 2:30 PM		
Accident Reported Date and Time	7/29/2024 2:35 PM		
s Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC, if any	SMB1409J - REAR PORTION GBL3956K (TP) - INSURED WITH AIG		
Prepared Date and Time	8/3/2024 9:50 AM		
Chassis Number	WMAA22ZZXD7001913		
Mileage			
Work Shop			
Repair Completion Date and Time			

	Section B - Summary of Rep	pair Estimates
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$2,561.40	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,499.40	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 days
Prepared / Adjusted By	ARC Manager Team	Taufikh
ARC / Surveyor Sign Off Date	05/08/2024 10:28 AM	5/8/24
Signature		taufikh
Remarks		Taufikh 97495749 WP 05/08/24 LUMPSUM RESURVEY AFTER REPAIR taufikh@lkkauto.com

	Section C - Quotation and Accident Invoice Details		
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 05/08/2024
User ID: choonhwee03

	Job Scope			Quotation from AR				Adjusted by Surveyo	r, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,060.00			795			
			\$1,060.00						
art 2 - Spray	Painting & P	anel Beating Rela	ted Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00				708		
			\$878.00						
art 3 - Other	Costs - Accid	lent and Accident	Repair Related Expens	e					
Job Scope			Quotation from ARC			Adjusted by Surveyor, if applicable			
otal Other Cos	sts								
art 4 - Spare	Parts / Mater	ial Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010298	VE	Control of the Contro	LAMP,STOP:LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	CRA 🗸
010299	VE		LAMP, INDICATOR: LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	CRA 🗸
010062	Body		COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	XR
009991	BODY RH		PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	XR
otal					\$3,583.20		\$3,201.75		
dded Spare	Parts / Materi	al Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number		Quantity	List Price \$	Discount (%)	Final Price (\$)	Tarana an	Surveyor Check