

2ND AUTO PTE LTD

15 Kaki Bukit Road 4 #01-53 Bartley Bizcentre Singapore 417808

Main Line : (65) 6741 6741

Fax : 6746 7939

N. F. Ariffin
14/6/24
1/5 & 5500
Alphard 14/6/24

14-Jun-24 624

Vehicle Reg No. : SLB 7997 A

Model : TOYOTA ALPHARD

Estimated repair cost for the vehicle as mentioned above

Qty	Description	Amt S(\$)
<u>List Items</u>		
1	Rear windscreen moulding <i>all</i>	\$ 181.90 ✓
1	Rear tailgate <i>DD/3af</i>	\$ 2,645.20 ✓
2	Rear tailgate dampers <i>11</i>	\$ 401.40 X
1	Rear tailgate inner board <i>de / Torn</i>	\$ 455.70 ✓
1	Rear tailgate chrome moulding <i>cro n/c</i>	\$ 455.70 X
1	Rear tailgate lock <i>Damage</i>	\$ 188.70 ✓
1	Rear tailgate logo <i>11</i>	\$ 88.00 X
2	Rear tailgate reflectors <i>11</i>	\$ 1,201.40 X
1	Rear tailgate rubber <i>7m1</i>	\$ 277.30 ✓
1	Rear tailgate "ALPHARD" emblem <i>'Vellfire' all</i>	\$ 120.70 ✓
1	Rear tailgate outer opening switch <i>11</i>	\$ 184.79 X
2	Rear taillamps <i>11</i>	\$ 1,377.40 X
1	Rear end panel <i>DD/3af</i>	\$ 945.20 ✓
1	Rear end panel inner garnish <i>7m1</i>	\$ 259.15 ✓
1	Rear keyless sensor <i>C12</i>	\$ 299.70 ✓
1	Rear sensor buzzer <i>SVC</i>	\$ 189.00 X
1	Rear bumper <i>DD/2e</i>	\$ 1,254.30 ✓
2	Rear bumper side <i>11</i>	\$ 803.90 X
2	Rear bumper brackets <i>11</i>	\$ 211.00 X
2	Rear bumper side brackets <i>11</i>	\$ 179.30 X
2	Rear bumper tow hook covers <i>11</i>	\$ 88.70 X
2	Rear bumper reflectors <i>11</i>	\$ 164.86 X
2	Rear bumper side retainers <i>11</i>	\$ 295.20 X
4	Rear bumper PDC sensors <i>11</i>	\$ 1,075.20 X
1	Rear bumper splash shield <i>11</i>	\$ 186.25 X
1	Rear floor board panel top board LH <i>worn</i>	\$ 455.00 ✓
1	Rear floor side board panel top board RH <i>worn</i>	\$ 185.00 ✓
2	Rear fender inner trims <i>11</i>	\$ 1,151.00 X
		\$ 15,320.95
Less 25%		\$ 3,830.24
		\$ 11,490.71

Special Nett Items

1	Rear windscreen sealant	<i>1u</i>	\$	80.00	<i>40 s/n</i>
1	Rear bumper clip (1 set)	<i>1u</i>	\$	80.00	<i>30 s/n</i>
			\$	160.00	

S/NLABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	<i>20</i>
2	To remove and refit inner garnishes. <i>upholstery</i>	\$	150.00	<i>80</i>
3	To remove and refit rear reverse sensor.	\$	180.00	<i>30</i>
4	To transfer rear tailgate mechanism and wiring assembly.	\$	80.00	<i>✓</i>
5	To remove and refit rear windscreen glass.	\$	180.00	<i>120</i>
6	To apply undercoating.	\$	180.00	<i>50</i>
7	Panel beating.	\$	1,600.00	<i>600</i>
8	To re-spray painting on the affected areas.	\$	1,500.00	<i>800</i>
		\$	3,950.00	

Grand Total :**\$ 15,600.71**

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p - 6710.15
252
5032.61
70
1780
6882.61
202
5506