

2ND AUTO PTE LTD

15 Kaki Bukit Road 4 #01-53 Bartley Bizcentre Singapore 417808

Main Line : (65) 6741 6741 Fax : 6746 7939

not Authorized
14/6/24
d/s \$5000/
photo taken
Edgys

14-Jun-24

Vehicle Reg No. : SLB 7997 A

Model : TOYOTA ALPHARD

Estimated repair cost for the vehicle as mentioned above

Qty	Description	Amt S(\$)
<u>List Items</u>		
1	Rear windscreen moulding <i>neu</i>	\$ 181.90 ✓
1	Rear tailgate <i>to 13m+</i>	\$ 1,956.70 ✓
2	Rear tailgate dampers <i>11</i>	\$ 401.40 X
1	Rear tailgate inner board <i>to 2/11m</i>	\$ 455.70 ✓
1	Rear tailgate chrome moulding <i>cro/nlc</i>	\$ 455.70 X
1	Rear tailgate lock <i>daye</i>	\$ 188.70 ✓
1	Rear tailgate logo <i>11</i>	\$ 88.00 X
2	Rear tailgate reflectors <i>11</i>	\$ 1,201.40 X
1	Rear tailgate rubber <i>twi</i>	\$ 277.30 ✓
1	Rear tailgate "ALPHARD" emblem <i>'vellfine' neu</i>	\$ 120.70 ✓
1	Rear tailgate outer opening switch <i>11</i>	\$ 184.79 X
2	Rear taillamps <i>11</i>	\$ 1,377.40 X
1	Rear end panel <i>to 13m+</i>	\$ 673.30 ✓
1	Rear end panel inner garnish <i>twi</i>	\$ 259.15 ✓
1	Rear keyless sensor <i>one</i>	<i>198.20</i> \$ 299.70 ✓
1	Rear sensor buzzer <i>su</i>	\$ 189.00 X
1	Rear bumper <i>to 12e</i>	<i>955.20</i> \$ 1,254.30 ✓
2	Rear bumper side <i>11</i>	\$ 803.90 X
2	Rear bumper brackets <i>11</i>	\$ 211.00 X
2	Rear bumper side brackets <i>11</i>	\$ 179.30 X
2	Rear bumper tow hook covers <i>11</i>	\$ 88.70 X
2	Rear bumper reflectors <i>11</i>	\$ 164.86 X
2	Rear bumper side retainers <i>11</i>	\$ 295.20 X
4	Rear bumper PDC sensors <i>su</i>	\$ 1,075.20 X
1	Rear bumper splash shield <i>11</i>	\$ 186.25 X
1	Rear floor board <i>panel top board L/R</i>	\$ 455.00 ✓
1	Rear floor side-board <i>panel top board R/L</i>	\$ 185.00 ✓
2	Rear fender inner trims <i>11</i>	\$ 1,151.00 X
		\$ 14,360.55
Less 25%		\$ 3,590.14
		\$ 10,770.41

<u>Special Nett Items</u>		
1	Rear windscreen sealant	1el
		\$ 80.00 40
1	Rear bumper clip (1 set)	1el
		\$ 80.00 30
		<u>\$ 160.00</u>

<u>S/N</u>	<u>LABOUR CHARGES</u>	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 150.00 80
3	To remove and refit rear reverse sensor.	\$ 180.00 30
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 80.00 60
5	To remove and refit rear windscreen glass.	\$ 180.00 120
6	To apply undercoating.	\$ 180.00 50
7	Panel beating.	\$ 1,600.00 600
8	To re-spray painting on the affected areas.	\$ 1,500.00 800
		<u>\$ 3,950.00</u>

Grand Total : \$ 14,880.41

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

1-5906.81
752
4430.14
70
1760
6260.14
202
5008