

EURO SUCCESS SERV PTE LTD

No. 1 Kaki Bukit Avenue 6

#02-03 AutoBay

SINGAPORE 417883

TEL.NO: 93365311 / FAX NO. 67411019

Email: eurosucccess0202@gmail.com

Estimate Report

To : Claim Department
 Attn :
 Tel :
 Fax :

Vehicles Number : SMD 470B
 Make and Model : M/BENZ CLA180 SB
 Date Of Accident : 28.07.2024

Attn: Motor Claim Department
 Estimated Repairs Costs

Qty	Nett List Items	Amount
1	Front Bumper	\$ 2,200.00 ✓
2	Front Bumper Brackets L-R @85.00	\$ 170.00 X
2	Front Bumper Side Mount L-R @97.20	\$ 194.40 X
2	Front Bumper Distance Sensor L-R - Outer @197.20	\$ 394.40 PC
2	Front Bumper Distance Sensor L-R - Inner @197.20	\$ 394.40 X
1	Front Bumper Sponge	\$ 125.00 ✓
1	Front Bumper Moulding	\$ 278.00 ✓
1	Front Grille	\$ 600.00 X
2	Front headlamp L-R @4800.00	\$ 9,600.00 PC
1	Front Headlamp Lower Bracket L-R @85.00	\$ 170.00 X
1	Front Headlamp Top Bracket L-R @85.00	\$ 170.00 X
1	Bonnet	\$ 2,300.00 X
1	Bonnet Centre Lock	\$ 185.00 X
1	Bonnet Lock	\$ 250.80 X
2	Bonnet Hinge @108.60	\$ 217.20 X
1	Bonnet Seal	\$ 125.50 X
1	Bonnet Insulator	\$ 350.10 X
1	Front Suspension L-R	\$ 1,980.00 X
Total		\$ 19,704.80
Less 10%		\$ 1,970.48
		\$ 17,734.32
Special nett item		
1	Front Tyre N/S	\$ 300.00 X
1	Front Rim N/S	\$ 550.00 X
1 set	Front Bumper Clips @50.00	\$ 50.00 ✓
4	Front Bumper Sensor @380.00	\$ 1,520.00 X
Total		\$ 2,420.00

Labour & Misc Charges

To knock and renew bonnet, front bumper	\$ 800.00 500
To respray replaced and affected panel Front Bumper, Bonnet	\$ 900.00 400
To carry out anti rust treatment	\$ 200.00 X
To check wiring for proper function	\$ 150.00 20
To check adjust headlamp height.	\$ 90.00
To carry out wheel alignment.	\$ 120.00 60
To provide towing service	\$ 100.00 X

not Authorized
 merous
 5/8/24
 2/5 \$ 4800/
 the photo Acc. rep
 3 days.

1784.32

166.80

3255.53 N/S

EURO SUCCESS SERV PTE LTD

No. 1 Kaki Bukit Avenue 6

#02-03 AutoBay

SINGAPORE 417883

TEL.NO: 93365311 / FAX NO. 67411019

Email: eurosucccess0202@gmail.com

Estimate Report

To : Claim Department
Attn :
Tel :
Fax :

Vehicles Number : SMD 470B D
Make and Model : M/BENZ CLA180 SB
Date Of Accident : 28.07.2024

Attn: Motor Claim Department
Estimated Repairs Costs

Qty	List Items	Amount	
		Total	\$
			2,360.00
		Grand Total	\$ 22,514.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

R-S\$29.85
102
4976.87
50
980
6006.87
202
4805.87