

SCL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416

Email: clappraiser@yahoo.com Hp: 9068 8689

Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: TMS Bikes Pte Ltd
C/o: TMS Bikes Pte Ltd
6 Gambas Way,
#03-09 Ascent @ Gambas, Singapore 756939

Date : 26 March 2024
Our ref : TMS/03/2401/TP

Accident Date : 24 February 2024
Inspection Date : 1 March 2024
Repairer Name : TMS Bikes Pte Ltd
6 Gambas Way,
#03-09 Ascent @ Gambas, Singapore 756939

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FT 7719 M
Make / Model : Yamaha FZN150
Chassis No : ME1RG1611G2001926
Engine No : G3E3E0038571

Year / Capacity : 2016 / 149 cc
Colour : Black
Mileage : 4561

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	Maxxis	110/70 -17	5 mm	Sport
Rear	Maxxis	140/70 -17	5.00 mm/ 5.00 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear and o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 82 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$3,000.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

L APPRAISER PTE LTD

Vehicle Registration No.: FT 7719 M

Our Ref No.:

TMS/03/2401/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front fender X ^{mm}	Damage	\$ 75.00	\$ 75.00
1	Front o/s signal X ^{mm}	Damage	\$ 68.00	\$ 68.00
1	O/s side mirror X ^{mm}	Damage	\$ 80.00	\$ 80.00
1	Handle-bar	Damage	\$ 145.00	\$ 145.00 ✓
1	Brake lever	Damage	\$ 28.00	\$ 28.00 ✓
1	Hand grip (1 set) X ^{mm}	Damage	\$ 80.00	\$ 80.00
1	Front o/s footrest X ^{mm}	Damage	\$ 42.00	\$ 42.00
1	Front o/s footrest bracket X ^{mm}	Damage	\$ 60.00	\$ 60.00
1	Brake pedal X ^{mm}	Damage	\$ 55.00	\$ 55.00
1	Rear o/s footrest X ^{mm}	Damage	\$ 42.00	\$ 42.00
1	Exhaust pipe assy X ^{mm}	Damage	\$ 655.00	\$ 655.00
1	Exhaust end cover X ^{mm}	Damage	\$ 68.00	\$ 68.00
1	Exhaust protector - black	Damage	\$ 75.00	\$ 75.00 ✓
1	Chain cover X ^{mm}	Damage	\$ 85.00	\$ 85.00 X
1	Rear o/s tailboard	Damage	\$ 155.00	\$ 155.00 ✓
2	Rear signals	Damage	\$ 136.00	\$ 136.00 ✓
1	Rear fender	Damage	\$ 95.00	\$ 95.00 ✓
1	Rear fender inner bracket	Damage	\$ 85.00	\$ 85.00 ✓
1	Rear taillamp	Damage	\$ 135.00	\$ 135.00 ✓
1	Rear rim X ^{mm}	Damage	\$ 550.00	\$ 550.00 X
			\$ 2,714.00	\$ 2,714.00
Less 10%			\$ 271.40	\$ 271.40
Total Cost - List Items			\$ 2,442.60	\$ 2,442.60

SPECIAL NETT ITEMS

1	Number plate (1 set)	Damage	\$ 28.00	\$ 15 28.00
1	Rear box X ^{mm}	Damage	\$ 280.00	\$ 280.00
1	Rear box bracket X ^{mm}	Damage	\$ 120.00	\$ 120.00
1	Rear tyre (Depreciation) X ^{mm}	Damage	\$ 400.00	\$ 200.00
Total Cost - Special Nett items			\$ 828.00	\$ 628.00

Total cost of parts

\$ 3,270.60	\$ 3,070.60
-------------	-------------

SL APPRAISER PTE LTD

Vehicle Registration No.: FT 7719 M

Our Ref No.: TMS/03/2401/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 3,270.60	\$ 3,070.60

LABOUR

1	To provide towing service.	\$ 50.00	\$ X 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 20 40.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 250 400.00
			<u>270</u>

GRAND TOTAL

\$ 3,880.60	\$ 3,560.60
-------------	-------------

768.60
15.00
270.00
1053.60
202
842
L/S - \$850 / 3 days