

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SLK 2163A**
Made : Honda
Model : Vezel Hybrid 1.5X A
Chassis No : RU31208833

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper <i>Delint</i>	1	\$ 505.80	\$ ✓ 505.80
2	Front Bumper Side Retainer RH <i>new</i>	1	\$ 18.90	\$ + 18.90
3	Front Bumper Side Retainer LH <i>new</i>	1	\$ 18.90	\$ + 18.90
4	Front Bumper Bracket RH <i>2</i>	1	\$ 29.60	\$ + 29.60
5	Front Bumper Bracket LH <i>2</i>	1	\$ 29.60	\$ + 29.60
6	Front Bumper Fog Lamp LH <i>2</i>	1	\$ 327.80	\$ + 327.80
7	Front Bumper Fog Lamp Garnish LH <i>new</i>	1	\$ 50.00	\$ + 50.00
8	Front Bumper Tow Cover <i>2</i>	1	\$ 29.80	\$ + 29.80
9	Front Bumper Reinforcement <i>2</i>	1	\$ 386.00	\$ + 386.00
10	Front Bumper Lower Grille <i>2</i>	1	\$ 108.30	\$ + 108.30
11	Front Bumper Lower Spoiler <i>new</i>	1	\$ 381.20	\$ + 381.20
12	Front Bumper Lower Rubber <i>new</i>	1	\$ 104.90	\$ + 104.90
13	Front Headlamp Assembly RH <i>new</i>	1	\$ 1,996.30	\$ + 1,996.30
14	Front Headlamp Assembly LH <i>cracked</i>	1	\$ 1,996.30	\$ ✓ 1,996.30
15	Front Headlamp Lower Bracket RH <i>2 of</i>	1	\$ 41.80	\$ + 41.80
16	Front Headlamp Lower Bracket LH <i>2 of</i>	1	\$ 41.80	\$ + 41.80
17	Front Grille Base <i>2</i>	1	\$ 391.80	\$ + 391.80
18	Front Grille Outer Garnish	1	\$ 357.80	\$ + 357.80
19	Front Grille Lower Moulding	1	\$ 106.20	\$ + 106.20
20	Front Grille Upper Centre Bracket <i>Not</i>	1	\$ 50.10	\$ + 50.10
21	Front Grille Bracket RH <i>Not</i>	1	\$ 16.70	\$ + 16.70
22	Front Grille Bracket LH	1	\$ 16.70	\$ + 16.70
23	Front Bonnet	1	\$ 981.50	\$ + 981.50
24	Front Support Panel	1	\$ 649.20	\$ + 649.20
25	Front Fender LH <i>Painted</i>	1	\$ 455.60	\$ ✓ 455.60
26	Front Fender Brace Bracket LH <i>new</i>	1	\$ 165.30	\$ + 165.30
27	Front Fender Inner Extension Panel LH <i>new</i>	1	\$ 115.20	\$ + 115.20

28	Front Fender Inner Gusset Panel LH <i>300</i>	1	\$	76.50	\$	<i>+</i> 76.50
29	Front Fender Outer Gusset Panel LH <i>300</i>	1	\$	76.50	\$	<i>+</i> 76.50
30	Front Fender Inner Cowling LH <i>new</i>	1	\$	120.60	\$	<i>+</i> 120.60
31	Front Fender Wheel Arch Garnish LH <i>De-hol</i>	1	\$	153.10	\$	<i>✓</i> 153.10
32	Front Wheel Rim LH <i>2</i>	1	\$	836.90	\$	<i>+</i> 836.90
33	Front Wheel Hub LH	1	\$	211.30	\$	<i>+</i> 211.30
34	Front Wheel Hub Bearing LH	1	\$	155.90	\$	<i>+</i> 155.90
35	Front Shock Absorber LH <i>NP</i>	1	\$	387.60	\$	<i>+</i> 387.60
36	Front Lower Arm LH <i>new</i>	1	\$	444.80	\$	<i>+</i> 444.80
37	Front Stabilizer Link	1	\$	53.40	\$	<i>+</i> 53.40
38	Front Knuckle Arm LH	1	\$	280.70	\$	<i>+</i> 280.70
39	Tie Rod End LH	1	\$	82.70	\$	<i>+</i> 82.70
40	Front Door Side Mirror Assembly LH <i>2</i>	1	\$	667.20	\$	<i>+</i> 667.20
41	Front Door Side Mirror Cover LH	1	\$	71.20	\$	<i>+</i> 71.20
42	Front Door LH	1	\$	903.20	\$	<i>+</i> 903.20
43	Front Door Upper Hinge LH <i>NP</i>	1	\$	38.50	\$	<i>+</i> 38.50
44	Front Door Lower Hinge LH <i>new</i>	1	\$	40.90	\$	<i>+</i> 40.90
45	Front Door Outer Glass Moulding LH	1	\$	55.60	\$	<i>+</i> 55.60
46	Front Door Lock LH	1	\$	225.00	\$	<i>+</i> 225.00
47	Front Door Weatherstrip LH (Top)	1	\$	85.00	\$	<i>+</i> 85.00
48	Front Door Weatherstrip LH (Lower)	1	\$	25.00	\$	<i>+</i> 25.00
49	Front Door Glass Channel LH	1	\$	88.00	\$	<i>+</i> 88.00
50	Front Door Glass Regulator with Motor LH <i>200</i>	1	\$	382.00	\$	<i>+</i> 382.00
51	Front Door Inner Trim Board LH <i>300</i>	1	\$	650.00	\$	<i>+</i> 650.00
52	Rocker Panel Garnish LH <i>new</i>	1	\$	415.30	\$	<i>+</i> 415.30

Parts Sub Total : \$ 15,900.00

20% Discount \$ 3,180.00

PARTS TOTAL : \$ 12,720.00

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Bumper Clips - Set <i>new</i>	1	\$ 50.00	\$ <i>30</i> 50.00
2	Front Bumper Grille Clips - Set <i>new</i>	1	\$ 30.00	\$ <i>+</i> 30.00
3	Front Bumper Fog Lamp Garnish LH Clips - Set <i>new</i>	1	\$ 30.00	\$ <i>+</i> 30.00
4	Front Fender Inner Cowling LH Clips - Set <i>new</i>	1	\$ 40.00	\$ <i>+</i> 40.00
5	Front Fender Wheel Arch Garnish LH Clips - Set <i>new</i>	1	\$ 30.00	\$ <i>✓</i> 30.00
6	Front Door Inner Trim Board LH Clips - Set <i>new</i>	1	\$ 50.00	\$ <i>+</i> 50.00
7	Rocker Panel Garnish LH Clips - Set <i>2</i>	1	\$ 50.00	\$ <i>+</i> 50.00
8	Front Bonnet Sealant <i>NP</i>	1	\$ 150.00	\$ <i>+</i> 150.00
9	Front Support Panel Sealant <i>new</i>	1	\$ 150.00	\$ <i>+</i> 150.00
10	Front Fender LH Sealant <i>✓</i>	1	\$ 150.00	\$ <i>+</i> 150.00

11	Front Door LH Sealant	1	\$ 150.00	\$ + 150.00
12	Radiator Coolant	1	\$ 60.00	\$ + 60.00
13	Front Tyre LH	1	\$ 350.00	\$ + 350.00
SPECIAL NETT TOTAL :				\$ 1,290.00

Nos.	LABOUR	TOTAL \$
1	To Panel Beat, Remove & Refix Parts	\$ 4w 1,600.00
2	To Spray Paint Affected Areas	\$ 4w 1,400.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Front Door LH Mechanism	\$ + 150.00
5	To apply anti rust on affected parts	\$ + 150.00
6	To Remove & Refix Aircon Condenser and Top Up Gas	\$ + 150.00
7	To Remove & Refix Radiator and Conduct Pressure Test	\$ + 150.00
8	To Conduct Four Wheel Alignment	\$ + 150.00
9	To Remove & Refix Front Undercarriage	\$ + 350.00
10	To Remove & Refix Front & Tyre and Conduct Wheel Balancing	\$ + 150.00
11	To Conduct Water Leak Test	\$ + 100.00
12	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ + 480.00
LABOUR TOTAL :		\$ 4,930.00

PARTS TOTAL : \$ 12,720.00

SPECIAL NETT TOTAL : \$ 1,290.00

LABOUR TOTAL : \$ 4,930.00

GRAND TOTAL : \$ 18,940.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/s 06/08/24.

0 8 Days