

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

TO	: CHINA TAIPING (SJA8820Z)	DATE	: 5-Aug-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX915I	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SNC4790U	TOTAL :	
MODEL / MAKE	: HONDA VEZEL	L/S -20% :	
CHASSIS NO.	: RU31224031	SUB TOTAL :	
ACCIDENT DETAIL			
DATE	: 5-Aug-24		
TIME	: 07:43HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Rear tailgate <i>1216.00 1099</i>	1	\$ 1,200.00	\$ 1,200.00
2	Rear bumper <i>12</i>	1	\$ 520.00	\$ 520.00
3	R/R tailgate reflector <i>17</i>	1	\$ 380.00	\$ 380.00
4	R/L tailgate reflector <i>17</i>	1	\$ 380.00	\$ 380.00
5	Rear end panel <i>12</i>	1	\$ 550.00	\$ 550.00
6	Rear end panel top garnish <i>17</i>	1	\$ 90.00	\$ 90.00
7	Rear spare tyre panel <i>12</i>	1	\$ 720.00	\$ 720.00
8	Rear tailgate lock <i>12</i>	1	\$ 220.00	\$ 220.00
9	Rear tailgate weatherstrip <i>12</i>	1	\$ 120.00	\$ 120.00
10	Vezel Emblem embblen <i>12</i>	1	\$ 45.00	\$ 45.00

*2pc Rear bumper sides**de/suc
280x2 = 560*

TOTAL PRICE	\$ 4,225.00
LESS -20%	\$ (845.00)
SUB TOTAL PRICE	\$ 3,380.00

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	Rear bumper reversement <i>reverse sensor 800 200 700</i>	1	\$ 300.00	\$ 300.00
2	Rear bumper clips <i>ref</i>	1	\$ 30.00	\$ 30.00

TOTAL	\$ 330.00
-------	-----------

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR BUMPER & END PANEL OUT TO FACILITATE REPAIRS & REPLACEMENT OF OF DAMAGED PARTS	\$	800.00	450	
TO RESPRAY REAR TAILGATE REAR END PANEL & REAR BUMPER	\$	800.00	500	
TO REMOVE & INSTALL REAR TAILGATE GLASS	\$	120.00	✓	
TO REMOVE & INSTALL REVERSE SENSOR TO FACILITATE REPLACEMENT OF PARTS	\$	100.00	30	

TOTAL \$ 1,820.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,710.00
 TOTAL LABOUR COST : \$ 1,820.00
 TOTAL REPAIR COST : \$ 5,530.00

APPROVED DETAILS

NO. OF REPAIR DAYS :
 REPAIR UNDER :
 DATE / TIME OF SURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER :
 EMAIL ADDRESS :
 DATE / TIME OF RE-SURVEY :

not Authorised to perform the work
 4 DAYS
 PART-BY-PART OR LUMP SUM
 6/8/24
 90096609
 2/5 \$2700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

p. 2564
 202
 2051.20
 230
 1100
 3381.20
 202
 2704.