



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO: 375654/00C

Not Authorised
6/8/24
3 dys 2/5 \$4500/
Height: 40cm

Carplate: SNC9119B
Chassis No: WBA2E320905H46314
Accident Date: 02/08/2024
Make & Model: BMW 216D GRAN TOURER

No.	Item	Price	✓/✗	Remarks
1	Front Bumper	\$ 1,526.95	1205.32	cut/rip ✓
2	Front Bumper Side Retainer LH	\$ 122.35		17 X
3	Front Headlamp LH	\$ 2,660.80	2363.65	Cut ✓
4	Front Headlamp Bracket LH	\$ 98.20		17 X
5	Front Bumper Reinforcement Beam	\$ 735.90		17 X
6	Front Bumper Reinforcement Beam Foam	\$ 311.25		17 X
7	Front Bumper Reinforcement Beam Bracket LH	\$ 226.10		17 X
8	Front Bumper Logo " H "	\$ 98.10		pu X
9	Front Bumper Sensor x 2 @ \$204.40/pc	\$ 408.80		8u X
10	Front Door LH	\$ 1,820.95		12 X
11	Front Door Hinge LH x2 @ \$112.50/pc	\$ 225.00		17 X
12	Front Fender LH	\$ 1,113.90	750.28	no/304 ✓
13	Front Fender Splash Guard LH	\$ 298.10		17 X
14	Front Bonet	\$ 2,160.25		17 X
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

	<u>Special Nett Items</u>	Price	✓/✗	Remarks
1	Front Bumper Clips (1 Set)	\$ 40.00		new 30 S/W
2	Front Tyre LH	\$ 580.00		src X
3	Front Tyre Rim LH	\$ 980.00		C47 450 S/W
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		20
2	Remove and Install New Front Sensor	\$ 120.00		30
3	Rewiring to Facilitate Repairs	\$ 150.00		20
4	Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works	\$ 320.00		11X
5	To carry out computer diagnosis for fault codes	\$ 180.00		11X
6	4 Wheel Allignment and Adjustment	\$ 150.00		60
7				
8				
9	Labour to remove and replace damaged parts, including refitting and repositioning of replaced parts	\$ 1,200.00		400
10	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 1,200.00		600
	Estimated No. of days for repairs and respray of all necessary	8 Days	3 dy	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 431922
52

4103.26

480

1130

5713.26

202

4500