

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNP3231E/2406091

13th June 2024

The Manager

Motor Claim Department

Auto & General Insurance (Singapore) Pte. Limited

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore 239924

Date of Accident : 12th June 2024

Location : Dunman Road

Third Party Claim Vehicle No : SKV 9038 L

Repair Cost For Vehicle No : SNP 3231 E Nissan Serena

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>R</i>	1	1,938.90	\$ 1,938.90 <i>x</i>
2	Rear boot cover weather stripe <i>11</i>	1	118.50	\$ 118.50 <i>x</i>
3	Rear boot cover emblem 'epower' <i>nel</i>	1	105.00	\$ 105.00 <i>✓</i>
4	Rear boot cover emblem 'highway star' <i>nel</i>	1	84.90	\$ 84.90 <i>✓</i>
5	Rear boot cover chrome moulding <i>11</i>	1	887.30	\$ 887.30 <i>x</i>
6	Rear bumper quarter panel <i>R</i>	1	428.90	\$ 428.90 <i>x</i>
7	Rear bumper fascia <i>to in</i>	1	1,574.00	\$ 1,574.00 <i>✓</i>
8	Rear bumper clips <i>nel</i>	1set	50.00	\$ 50.00 <i>✓</i>
9	Rear bumper sensor (LH & centre outer) <i>8u</i>	2	258.20	\$ 516.40 <i>x</i>
10	Rear bumper side retainer L&R (horizontal) <i>11</i>	2	36.20	\$ 72.40 <i>x</i>
11	Rear bumper side retainer L&R (vertical) <i>11</i>	2	36.20	\$ 72.40 <i>x</i>
12	Rear bumper lower side bracket L&R <i>11</i>	2	36.20	\$ 72.40 <i>x</i>
13	Tail lamp RH <i>sen/alc</i>	1	623.90	\$ 623.90 <i>x</i>
14	Rear bumper lower lip (s/nett) <i>cu</i>	1	1,300.00	\$ 1,300.00 <i>✓</i>
				\$ 7,845.00 <i>SN</i>

102

not allowed
in
now
3/7/24
Take photo & keep it
3 days
P/P # 4670-91

Not item

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNP3231E/2406091

13th June 2024

Balance b/f \$ 7,845.00

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear boor cover, rear quarter panel, remove & install all damage parts, straighten & re-align body

\$ 1,080.00

400

Tuff-kote on damage parts

11 \$ 40.00

X

Spray painting on damage parts

\$ 1,580.00

500

Remove & refix rear bumper sensor

\$ 80.00

30

Check all lighting after repairs

\$ 40.00

20

Coating

\$ 800.00

360

Labour Charge

\$ 3,620.00

Total Amount

\$ 11,465.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 1813.90
102

2- 1632.51

S.N - 1728.40

4- 1310

4670.91

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNP3231E/2406091

01th August 2024

The Manager
Motor Claim Department
Auto & General Insurance (Singapore) Pte. Limited
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

Date of Accident : 12th June 2024

Location : Dunman Road

Third Party Claim Vehicle No : SKV 9038 L

Repair Cost For Vehicle No : SNP 3231 E Nissan Serena

Supplementary of Parts

<u>No.</u>	<u>Particulars</u>		<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper inner bracket L&R (s/net)	ner	2	107.10	\$ 214.20
2	Rear bumper outer bracket L&R (s/net)	ner	2	107.10	\$ 214.20
					<u>\$ 428.40</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.