

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SNP3231E/2406091

01th August 2024

The Manager
Motor Claim Department
Auto & General Insurance (Singapore) Pte. Limited
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

Date of Accident : 12th June 2024

Location : Dunman Road

Third Party Claim Vehicle No : SKV 9038 L

Repair Cost For Vehicle No : SNP 3231 E Nissan Serena

Supplementary of Parts

<u>No.</u>	<u>Particulars</u>		<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper inner bracket L&R (s/net)	<i>net</i>	2	107.10	\$ 214.20
2	Rear bumper outer bracket L&R (s/net)	<i>net</i>	2	107.10	\$ 214.20
					<u>\$ 428.40</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.