

India

辉 阳 汽 车 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/08/2024

Owner: HYMS CAR LEASING PTE LTD

Not Authorized
Manny Bypain
8 days
1/10/24 \$7100/2

ESTIMATE TO REPAIR TOYOTA SIENTA HYBRID - SDU9908P

1pc	front bumper	1171.80	Bumper	\$ 1,250.20	✓
1pc	front bumper LH side garnish		Sen	\$ 181.20	✓
3pcs	front bumper LH side garnish clip @\$8.00		mes	\$ 24.00	✓
1pc	front bumper LH side retainer		DIY	\$ 121.50	✓
1pc	front LH headlamp		m3cm	\$ 1,580.50	✓
1pc	front LH fender		B	\$ 685.50	✓
1pc	front LH fender inner shield		DIY	\$ 281.50	✓
10pcs	front LH fender inner shield clip @\$5.00		na	\$ 50.00	✓
1pc	front LH fender top garnish		Sen	\$ 181.20	X
1pc	front LH wheel house outer panel		R	\$ 385.50	X
1pc	front LH rim	P-1	DD	\$ 581.50	✓
1pc	front LH rim half cap		m3	\$ 158.20	✓
1pc	front LH knuckle arm		B	\$ 481.50	✓
1pc	front LH knuckle bearing	301-	me	\$ 425.20	✓
1pc	front LH absorber		B	\$ 450.50	✓
1pc	front LH lower arm		DIY	\$ 381.50	✓
1pc	front LH linkage		DIY	\$ 181.50	✓
1pc	front LH side mirror		R	\$ 581.50	X
1pc	front LH side mirror cover		R	\$ 195.20	X
1pc	front LH door		B	\$ 985.20	✓
1pc	front LH door prille		R	\$ 985.20	X
2pcs	front LH door hinge @\$181.50	Upper R X	Lower R	\$ 363.00	X
1pc	front LH door protector		me	\$ 281.50	✓
8pcs	front LH door protector clip @\$5.00		me	\$ 40.00	✓
1pc	front LH door inner lock		R	\$ 481.50	✓
1pc	front LH door inner rubber		Sen	\$ 281.20	X
1pc	front LH door glass motor & gear		Sen	\$ 481.20	X
1pc	front LH door firm sticker		me	\$ 121.50	✓
1pc	rear LH door		R	\$ 1,250.20	X
1pc	rear LH door protector		me	\$ 281.20	✓
1pc	rear LH door firm sticker		me	\$ 121.50	X

less 25%
balance c/f

\$ 13,850.90
\$ 3,462.73
\$ 10,388.18



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/08/2024

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA SIENTA HYBRID - SDU9908P

balance b/f

\$ 10,388.18

1pc front LH tyre

120sn
W s.nett \$ 250.00 602sn
200

remove & refit dashboard
remove & refix front LH undercarriage
remove & refix front windscreen glass
remove & refit LH 2 door glass
towing fee
alignment
sealant
tuffkote
wiring
spray painting
labour charges
Total

UN\$ 350.00 X
\$ 380.00 200
nn\$ 120.00 X
\$ 150.00 601
(Bill) \$ 120.00 601
\$ 80.00 601
nn\$ 120.00 X
\$ 120.00 601
\$ 150.00 201
\$ 1,600.00 1000
\$ 1,600.00 700
\$ 15,428.18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

