



SKYLINK
世凯联集团

SKYLINK ENGINEERING PTE LTD

1 Bukit Batok Crescent Wcega Plaza #08-52 S658064

Tel : +65 6908 1928 Fax : +65 6908 1929

Co Reg/CST. No. 202100108N

www.skylink.com.sg

ESTIMATION REPORT

Vehicle No : SNQ8162H

Make & Model : HONDA, FREED HYBRID 1.5G CVT, GB73259930

Year of Manufacture : 2024

Estimation No. : E24080002

Date : 05/08/2024

No.	Code	Description	Qty	U/P	Amt
Section: PARTS					
1		TAILGATE <i>bl</i>	1.00	2,785.00	2,785.00
2		REAR BUMPER <i>repair</i>	1.00	1,090.00	1,090.00
3		FREED EMBLEM <i>m</i>	1.00	85.20	85.20
4		HYBRID EMBLEM <i>m</i>	1.00	85.20	85.20
5		HONDA EMBLEM <i>m</i>	1.00	79.30	79.30

Subtotal S\$ 4,124.70

Discount S\$ 0.00

Total S\$ 4,124.70

Section: S/NETT

6	SN00001	REAR NUMBER PLATE W/ CASING <i>xm</i>	1.00	50.00	50.00
7	SN00006	GLASS SEALANT <i>m</i>	1.00	40.00	40.00

Subtotal S\$ 90.00

Discount S\$ 0.00

Total S\$ 90.00

Section: LABOUR

8	L0006	TRANSFER PARTS TO NEW TAILGATE	1.00	120.00	120.00
9	L0001	LABOUR TO REPLACE DAMAGED PARTS	1.00	800.00	800.00
10	L0003	SPRAY PAINT	1.00	600.00	600.00
11	L0005	REMOVE AND INSTALL REAR WINDSCREEN	1.00	200.00	200.00

Subtotal S\$ 1,720.00

Discount S\$ 0.00

Total S\$ 1,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Remarks:

DOA: 31/07/2024

1449.68

40.00

1080.00

2569.68

Rasm

Hp 90010068

4 days

p/p

07/08/24

Reg by print

PARTS Subtotal S\$ 4,124.70

S/NETT Subtotal S\$ 90.00

LABOUR Subtotal S\$ 1,720.00