

Estimate Repair Cost of :SNB5901R
Vehicle Model:F26/216D
WBA2E320805H46143.

Spare Parts:

Rear PDC Sensor-
Rear PDC bushing
Rear Bumper Cover
Rear Bumper trim panel-prime
Rear Bumper Tow hook cover
Guide Bumper lateral support
Rear Bumper ~~re. for. cam.~~
Rear Bumper Wheel arch cover
~~Rear bumper reflector~~
Combination nut
Clips
Hex Nut bolt
Clips
Plug In nut
Expanding nut
Fillistre head screw
expanding rivet
Hex Nut plate
Hex Bolt

4	o/s mofhuton	\$1,078.60	IPC	269.68
4	rel	\$22.60		
1	o/s	\$288.14		
1	o/s	\$1,078.50		
1	cut	\$56.50		
2	o/s cno	\$345.20	IPC	172.60
1	benf	\$369.90		
2	11	\$156.94	X	
2	o/s cno	\$165.20	IPC	82.60
10	11	\$16	X	
10	11	\$12.50		
10	11	\$16.50	X	
10	11	\$12.50	X	
10	11	\$32.00	X	
10	11	\$5.50	X	
10	11	\$11.00	X	
10	11	\$5.00	X	
10	11	\$18.50	X	
10	11	\$16.00	X	
SUB TOTAL		\$3,441.88		

Labour

To check wiring at rear bumper & repair if required \$120.00 20
To conduct panel beat, repair and replace accident affected items \$1,500.00 300
To putty & respray for all damaged areas \$1,300.00 600
To perform Rust Proofing 11 \$120.00 X
To replace Damaged PDC Sensor \$120.00 30

SUB TOTAL \$3,160.00

Grand Total \$6,601.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
mercy
90096608

7/8/24
2/5 \$2500

4 days
take photo after 1 yr

2352.59
52
2235.34
950
3185.34
202
2548.